



Mercedes-Benz

 **GI6DYF**

report date: 2024-03-29

General information

Make	MERCEDES
Model	ML ML 280 CDI SPORT
Colour	Silver
Year of manufacture	2009
Top speed	127 mph
0 - 60 mph	9.8 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	440 Nm at 2.800 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	21.9 mpg
Consumption extra urban	35.3 mpg
Consumption combined	28.8 mpg
CO2 emission	254 g/km
CO2 label	L






Internet history

Entry 1

Date	2021-05-22
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-11
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	43
Total items failed	10

MOT #16 2023-10-11 14:06

MOT test number 721652276291

Result ✓ Passed

Next expiry date 2024-10-11

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15 2022-10-11 11:38

MOT test number 209116307438

Result ✓ Passed

**MOT #14**

2021-10-07 10:49

MOT test number

153880498455

Result

✓ Passed

Advice

Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #13

2020-10-12 14:37

MOT test number

904236836755

Result

✓ Passed

Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #12

2020-10-12 09:01

MOT test number

329052198067

Result

✗ Failed

Advice

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail

Nearside Front Brake hose excessively deteriorated (1.1.12 (b) (ii))

Advice

Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail

Offside Front Brake hose excessively deteriorated (1.1.12 (b) (ii))

Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #11**

2019-04-02 16:09

MOT test number

788622435531

Result

✓ Passed

Advice Offside Rear Brake pipe corroded, covered in grease or other material TO BRAKE HOSE (1.1.11 (c))

Advice Tyre worn close to legal limit/worn on edge BOTH REAR EDGES & ON 2 MM (5.2.3 (e))

Advice PARKING BRAKE ONLY JUST MET REQUIREMENTS 17%

Advice Brake disc worn, but not excessively BOTH SIDES REAR (1.1.14 (a) (i))

Advice Offside Front Brake pipe corroded, covered in grease or other material TO BRAKE HOSE (1.1.11 (c))

MOT #10

2019-03-29 15:52

MOT test number

869047872335

Result

✗ Failed

Advice Offside Front Brake pipe corroded, covered in grease or other material TO BRAKE HOSE (1.1.11 (c))

Fail Offside Front Position lamp not working (4.2.1 (a))

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Nearside Rear Lower Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Coil spring fractured or broken BOTH SIDE REAR BROKEN (5.3.1 (b) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material TO BRAKE HOSE (1.1.11 (c))

Fail Offside Rear Upper Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Tyre worn close to legal limit/worn on edge BOTH REAR EDGES & ON 2 MM (5.2.3 (e))

Fail Offside Front Brake hose excessively damaged CENTRAL MOUNTING BRACKET BROKEN (1.1.12 (b) (ii))

Advice Brake disc worn, but not excessively BOTH SIDES REAR (1.1.14 (a) (i))

Advice PARKING BRAKE ONLY JUST MET REQUIREMENTS 18%

**MOT #9** 2018-03-27 16:28**MOT test number** 380736900789**Result** ✓ Passed**Advice** Offside Front Brake pipe slightly corroded TO BRAKE HOSE (3.6.B.2c)**Advice** Tyre worn close to the legal limit BOTH REAR (4.1.E.1)**Advice** Offside Rear Brake pipe slightly corroded TO BRAKE HOSE (3.6.B.2c)**Advice** Offside Rear Nail in tyre**MOT #8** 2017-03-29 10:39**MOT test number** 154136594011**Result** ✓ Passed**MOT #7** 2016-09-02 08:45**MOT test number** 918531310463**Result** ✓ Passed**Advice** Nearside Brake pipe slightly corroded Front to rear (3.6.B.2c)**Advice** Oil leak**Advice** Offside Brake pipe slightly corroded front to rear (3.6.B.2c)**Advice** Both front tyres bald on outer edge**MOT #6** 2015-07-26 12:36**MOT test number** 515207005203**Result** ✓ Passed**Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)

**MOT #5** 2015-07-25 16:51**MOT test number** 367176705499**Result** ✗ Failed**Fail** Nearside Rear Seat belt retracting mechanism defective (5.2.5b)**Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)**Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**MOT #4** 2014-07-19 12:00**MOT test number** 158430704291**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-07-12 11:58**MOT test number** 275953593446**Result** ✓ Passed**MOT #2** 2012-06-25 17:39**MOT test number** 508797172161**Result** ✓ Passed**MOT #1** 2012-06-25 17:39**MOT test number** 259687972188**Result** ✗ Failed**Pass with rectification** Nearside Front All position lamps not working (1.1.A.3b)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
11 October 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	11 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-03-26
Last registration	2023-10-11
Complete history	See info



Registration #1	2009-03-26	9 mi
Registration #2	2012-06-25	40.049 mi
Registration #3	2013-07-12	53.807 mi
Registration #4	2014-07-19	66.329 mi
Registration #5	2015-07-25	78.822 mi
Registration #6	2015-07-26	78.825 mi
Registration #7	2016-09-02	92.922 mi
Registration #8	2017-03-29	97.157 mi
Registration #9	2018-03-27	103.646 mi
Registration #10	2019-03-27	111.277 mi
Registration #11	2019-03-27	111.277 mi
Registration #12	2019-03-27	111.277 mi
Registration #13	2019-03-27	111.277 mi
Registration #14	2019-03-27	111.277 mi
Registration #15	2019-03-27	111.277 mi
Registration #16	2019-03-27	111.277 mi
Registration #17	2019-03-27	111.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1911 mm
Height	1884 mm
Length	4780 mm
Wheel base	2915 mm

Additional information

Fuel tank capacity	95 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	64294040785848