



report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 260 SWB P/V
Colour	White
Year of manufacture	2004
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	180 Nm at 2.250 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	39.8 mpg
Consumption combined	34.9 mpg



LABEL UNKNOWN

**MOT history**

MOT expiry date	2020-12-12
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	28
Total items failed	3

MOT #15 2019-11-18 13:19**MOT test number** 921632272745**Result** Passed**Next expiry date** 2020-12-12**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Front Inner Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Advice** Offside Rear Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Advice** Offside Rear Lower Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Front Lower Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Advice** Nearside Rear Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Advice** Lower Integral body structure is corroded but structural rigidity is not significantly reduced all (6.1.1 (c) (i))**MOT #14** 2018-12-13 10:53**MOT test number** 522156451478**Result** Passed**Advice** Lower Integral body structure is corroded but structural rigidity is not significantly reduced all (6.1.1 (c) (i))

**MOT #13** 2017-09-14 08:34**MOT test number** 321162962264**Result** ✓ Passed**Advice** Lower Vehicle structure has slight corrosion all (6.1.A.1)**Advice** Lower Body has slight corrosion all (6.1.B.2)**MOT #12** 2016-09-05 08:41**MOT test number** 465170469493**Result** ✓ Passed**Advice** Lower Body has slight corrosion all (6.1.B.2)**MOT #11** 2015-08-04 16:46**MOT test number** 748026115242**Result** ✓ Passed**Advice** Upper Body has slight corrosion (6.1.B.2)**Advice** Lower Body has slight corrosion (6.1.B.2)**MOT #10** 2014-07-31 12:23**MOT test number** 735152714265**Result** ✓ Passed**Advice** Lower Body has slight corrosion (6.1.B.2)**Advice** Offside Outer Body has slight corrosion (6.1.B.2)

**MOT #9** 2013-07-16 12:36**MOT test number** 457767493109**Result** ✓ Passed

- Advice** Nearside Outer Body has slight corrosion (6.1.B.2)
- Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Upper Body has slight corrosion (6.1.B.2)
- Advice** Offside Outer Body has slight corrosion (6.1.B.2)

MOT #8 2012-06-29 10:31**MOT test number** 718231282143**Result** ✓ Passed

- Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)

MOT #7 2012-06-29 10:31**MOT test number** 605071182167**Result** ✗ Failed

- Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)
- Pass with rectification** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

MOT #6 2011-06-24 15:02**MOT test number** 807715571159**Result** ✓ Passed

- Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Deterioration of nearside windscreen wiper blade.

**MOT #5** 2010-06-16 11:32**MOT test number** 640337860144**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #4** 2010-06-16 11:32**MOT test number** 223227660149**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #3** 2009-06-20 15:53**MOT test number** 954421379121**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Nearside primary rearview mirror missing, secondry mirror prvides adequate view to the rear.**MOT #2** 2008-06-21 13:39**MOT test number** 962513178152**Result** ✓ Passed**MOT #1** 2007-06-14 09:19**MOT test number** 130895267168**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EA04GGV
Plate since	2019-03-28
Current registration	EA04GGV
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2004-05-26
Last registration	2019-11-18
Complete history	See info



Registration #1	2004-05-26	7 mi
Registration #2	2007-06-14	56.081 mi
Registration #3	2008-06-21	76.652 mi
Registration #4	2009-06-20	101.927 mi
Registration #5	2010-06-16	121.213 mi
Registration #6	2011-06-24	128.257 mi
Registration #7	2012-06-29	134.584 mi
Registration #8	2013-06-29	141.911 mi
Registration #9	2014-06-29	149.238 mi
Registration #10	2015-06-29	156.565 mi
Registration #11	2016-06-29	163.892 mi
Registration #12	2017-06-29	171.219 mi
Registration #13	2018-06-29	178.546 mi
Registration #14	2019-06-29	185.873 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2360 mm
Height	1970 mm
Length	4834 mm

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Engine number	4A49220