



A067VHR

report date: 2024-03-29

General information

Make	SUZUKI
Model	SWIFT SZ-T BOOSTERJET
Colour	Red
Year of manufacture	2017
Top speed	121 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	170 Nm at 3.500 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	49.5 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	104 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-02-04
Pictures	9
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-05-11
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	21
Total items failed	2

MOT #6	2023-05-09 09:33
MOT test number	333167672444
Result	✓ Passed
Next expiry date	2024-05-11
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5	2023-05-09 09:33
MOT test number	220190790525
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #4**

2022-05-12 08:35

MOT test number

700775437853

Result

✓ Passed

- Advice** Offside Front Tyre slightly damaged/cracking or perishing cracked and perished (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracked and perished (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracked and perished (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))

MOT #3

2022-05-10 09:21

MOT test number

693384364383

Result

✗ Failed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracked and perished (5.2.3 (d) (ii))
- Advice** Items removed from driver's view prior to test fluffy dice and air freshener
- MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracked and perished (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))
- MAJOR** Central Rear Seat belt buckle not functioning as intended buckle does not lock every time (7.1.2 (d))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing cracked and perished (5.2.3 (d) (ii))
- Minor** Offside Front Windscreen wiper blade defective split but still clears (3.4 (b) (i))

MOT #2

2021-05-06 14:23

MOT test number

307313772616

Result

✓ Passed



MOT #1	2020-11-24 12:41
MOT test number	832321673050
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing Tyre starting to crack in between tread (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing Tyre starting to crack in between tread (5.2.3 (d) (ii))
Advice	Hand brake near end of travel (10 Clicks)
Advice	Offside Front Tyre slightly damaged/cracking or perishing Tyre starting to crack in between tread, 185/55 R16 83v (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing Tyre starting to crack in between tread (5.2.3 (d) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
11 May 2024

Tax status	Valid until 1 May
Days left	366
MOT expiry date	11 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-11-30
Last registration	2023-05-09
Complete history	See info



Registration #1	2017-11-30	16 mi
Registration #2	2020-11-24	20.823 mi
Registration #3	2021-05-06	21.736 mi
Registration #4		
Registration #5		
Registration #6		
Registration #7		
Registration #8		

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	88%
Children	75%
Pedestrian	69%
Safety systems	44%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1735 mm
Height	1495 mm
Length	3840 mm
Wheel base	2450 mm
Kerb weight	865 kg
Max. allowed weight	1380 kg

Additional information

Fuel tank capacity	37 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	K10C-1055105