




report date: 2024-03-28

General information

Make	KIA
Model	SORENTO CRDI XE
Colour	Blue
Year of manufacture	2006
Top speed	104 mph
0 - 60 mph	11.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	313 Nm at 2.000 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	23.9 mpg
Consumption extra urban	38.7 mpg
Consumption combined	31.7 mpg
CO2 emission	223 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-06-12
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-05
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	31
Total items failed	13

MOT #21	2024-03-14 12:12
MOT test number	389555807336
Result	✓ Passed
Next expiry date	2025-04-05
Advice	Front Body panel slightly loose bumper (6.2.1 (a) (i))

MOT #20	2023-04-06 15:20
MOT test number	340189225248
Result	✓ Passed
Advice	Nearside Rear Inner Seat belt anchorage prescribed area is corroded but not considered excessive sill panel (7.1.1 (a) (i))
Advice	General surface corrosion on underside of vehicle
Advice	Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #19**

2023-03-16 10:20

MOT test number

147229896202

Result

✗ Failed

- Fail** Front Prop shaft joint excessively worn (6.1.7 (c) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** General surface corrosion on underside of vehicle
- Fail** Offside Front Anti-roll bar pin or bush excessively worn D bush (5.3.4 (a) (i))
- Fail** Nearside Rear Seat belt webbing significantly weakened (7.1.2 (b) (ii))
- Fail** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Seat belt anchorage prescribed area is corroded but not considered excessive inner sill panel (7.1.1 (a) (i))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Fail** Nearside Front Anti-roll bar pin or bush excessively worn D bush (5.3.4 (a) (i))
- Advice** High level brake light inoperative

MOT #18

2022-03-02 09:17

MOT test number

587429329614

Result

✓ Passed

- Advice** Headlamp lenses fading
- Advice** Front cv joints noisy
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Various brake pipes corroding
- Advice** Parking brake effort just met

**MOT #17**

2022-03-01 12:18

MOT test number

590537966114

Result**✗ Failed****Advice** Front cv joints noisy**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Rear Suspension arm attachment bracket/mounting corroded and seriously weakened axle casing bracket (5.3.3 (b) (i))**Advice** Various brake pipes corroding**Advice** Parking brake effort just met**Advice** Headlamp lenses fading**MOT #16**

2021-02-02 15:04

MOT test number

830035032240

Result**✓ Passed****Advice** Front propshaft gaiter leaking grease**Advice** Front headlamps getting cloudy.**MOT #15**

2021-02-02 15:04

MOT test number

314751289871

Result**✗ Failed****Advice** Front propshaft gaiter leaking grease**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Front headlamps getting cloudy.**MOT #14**

2020-02-19 16:46

MOT test number

569387790619

Result**✓ Passed**

**MOT #13** 2020-02-19 09:16**MOT test number** 527224173926**Result** ✗ Failed**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #12** 2019-02-19 09:10**MOT test number** 879688805238**Result** ✓ Passed**Advice** Slight play in both rack ends.**MOT #11** 2018-02-21 11:47**MOT test number** 774824577230**Result** ✓ Passed**MOT #10** 2017-02-23 12:08**MOT test number** 684081049479**Result** ✓ Passed**Advice** Deep cut in offside front tyre**Advice** Rear tyres worn low/close to limits**MOT #9** 2016-02-17 17:01**MOT test number** 137892836964**Result** ✓ Passed**Advice** Chip in the windscreen

**MOT #8** 2016-02-17 11:04**MOT test number** 238832615992**Result** ✗ Failed**Advice** Chip in the windscreen**Fail** Brake cable has a seized clevis joint pivot (3.5.1c)**Advice** Offside front tyre is worn on the inner edge & cracking**Fail** Parking brake: efficiency below requirements (3.7.C.1b)**Fail** Offside Rear Brake pipe fouled by moving parts handbrake cable is rubbing (3.6.B.2a)**MOT #7** 2015-02-23 09:03**MOT test number** 929234455003**Result** ✓ Passed**MOT #6** 2014-02-20 11:06**MOT test number** 199041054076**Result** ✓ Passed**MOT #5** 2013-02-11 10:30**MOT test number** 235282843083**Result** ✓ Passed**Notice** Nearside rear parking brake cable stirr in operation**MOT #4** 2012-02-22 08:49**MOT test number** 105843652057**Result** ✓ Passed**MOT #3** 2011-02-10 15:36**MOT test number** 685611941045**Result** ✓ Passed



MOT #2	2010-02-16 16:25
MOT test number	164427240064
Result	✓ Passed
MOT #1	2009-02-17 08:57
MOT test number	541078949027
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
5 April 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	5 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	EY55BVK
Plate since	2019-03-28
Current registration	EY55BVK
Plate since	2019-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-02-23
Last registration	2024-03-14
Complete history	See info



Registration #1	2006-02-23	27 mi
Registration #2	2009-02-17	43.851 mi
Registration #3	2010-02-16	48.501 mi
Registration #4	2011-02-10	51.354 mi
Registration #5	2012-02-22	54.602 mi
Registration #6	2013-02-11	58.753 mi
Registration #7	2014-02-20	65.306 mi
Registration #8	2015-02-23	72.661 mi
Registration #9	2016-02-17	79.970 mi
Registration #10	2016-02-17	79.970 mi
Registration #11	2017-02-23	88.761 mi
Registration #12	2018-02-21	96.174 mi
Registration #13	2019-02-20	105.277 mi
Registration #14	2019-02-20	105.277 mi
Registration #15	2019-02-20	105.277 mi
Registration #16	2019-02-20	105.277 mi
Registration #17	2019-02-20	105.277 mi
Registration #18	2019-02-20	105.277 mi
Registration #19	2019-02-20	105.277 mi
Registration #20	2019-02-20	105.277 mi
Registration #21	2019-02-20	105.277 mi
Registration #22	2019-02-20	105.277 mi
Registration #23	2019-02-20	105.277 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1885 mm
Height	1805 mm
Length	4590 mm
Wheel base	2710 mm
Kerb weight	2079 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4CB5840937