



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV4 VVTI GX
Colour	Black
Year of manufacture	2001
Top speed	112 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	146 BHP
Max. torque	193 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	211 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-05
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2023-05-04
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	55
Total items failed	6

MOT #192022-04-26 08:27

MOT test number845649984894

Result✓ Passed

Next expiry date2023-05-04

- Advice**Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice**Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice**Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice**Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Minor**Headlamp lens slightly defective both (4.1.1 (b) (i))
- Advice**Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice**Brake pipe corroded, covered in grease or other material front to rears (1.1.11 (c))



MOT #18 2021-05-05 16:27

MOT test number 197461383343

Result ✓ Passed

Advice Front Suspension arm corroded but not seriously weakened x2 (5.3.3 (b) (i))

Advice Coil spring corroded front/rear (5.3.1 (b) (i))

Advice Front h.lights poor beam image

Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Underbody corroded/undersealed

MOT #17 2021-05-05 16:02

MOT test number 571057630693

Result ✗ Failed

Advice Front h.lights poor beam image

Advice Front Suspension arm corroded but not seriously weakened x2 (5.3.3 (b) (i))

Advice Coil spring corroded front/rear (5.3.1 (b) (i))

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Underbody corroded/undersealed

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #16**

2019-04-26 08:57

MOT test number

886841740000

Result

✓ Passed

- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear greased (1.1.11 (c))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Corrosion to underside of vehicle
- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear greased (1.1.11 (c))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view b zone (3.2 (a) (i))

MOT #15

2018-04-26 13:13

MOT test number

425578735259

Result

✓ Passed

- Advice** Offside Front coil spring corroded (2.4.C.1b)
- Advice** Rear brake pipes greased
- Advice** Corrosion to both front jacking points
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)

**MOT #14**

2018-04-19 09:01

MOT test number

343848677475

Result**✗ Failed****Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Corrosion to both front jacking points**Fail** Offside Rear Outer Suspension component mounting prescribed area is excessively corroded sill (2.4.A.3)**Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Offside Front coil spring corroded (2.4.C.1b)**Fail** Offside Rear Inner Suspension component mounting prescribed area is excessively corroded sill (2.4.A.3)**Advice** Rear brake pipes greased**MOT #13**

2017-04-12 10:58

MOT test number

252532648346

Result**✓ Passed****Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Rear brake pipes greased**Advice** Offside Front Inner Brake pad(s) wearing thin (3.5.1g)**MOT #12**

2016-04-07 08:53

MOT test number

532198962526

Result**✓ Passed****Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Rear brake pipes greased

**MOT #11** 2016-04-07 08:53**MOT test number** 570319754661**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Rear brake pipes greased**Pass with rectification** Rear fog lamp not working (1.3.2b)**MOT #10** 2015-04-27 12:07**MOT test number** 246747015422**Result** ✓ Passed**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Rear brake pipes greased**MOT #9** 2014-04-10 10:04**MOT test number** 809870904180**Result** ✓ Passed**Notice** Front to rear brake pipes greased**MOT #8** 2013-04-27 09:42**MOT test number** 405707713127**Result** ✓ Passed**Notice** Rear exhaust flange cracked but not excessively leaking**Notice** Slight corrosion to rear brake pipes



MOT #7	2012-04-19 15:20
---------------	------------------

MOT test number	289030312183
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2011-04-12 09:20
---------------	------------------

MOT test number	915652201115
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2010-04-20 09:42
---------------	------------------

MOT test number	324720810102
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2009-04-03 14:55
---------------	------------------

MOT test number	693353099036
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2008-04-14 10:36
---------------	------------------

MOT test number	372295108128
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2007-04-16 16:31
---------------	------------------

MOT test number	102866007116
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2007-04-13 09:58
---------------	------------------

MOT test number	240513407400
------------------------	--------------

Result	✗ Failed
---------------	----------

Notice	Rear wiper blade split
---------------	------------------------

Fail	Nearside Rear brake disc excessively pitted (3.5.1h)
-------------	--

Fail	Offside Rear brake disc excessively pitted (3.5.1h)
-------------	---



Tax & MOT check

X

Untaxed

Tax expired:
5 August 2023

X

MOT

Expired:
4 May 2023

Tax status	Expired at 5 August 2023
Days left	269 days too late
MOT expiry date	4 May 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	Y796 WDO
Plate since	2019-03-29
Current registration	Y796 WDO
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2001-07-12
Last registration	2022-04-26
Complete history	See info



Registration #1	2001-07-12	28 mi
Registration #2	2007-04-13	22.456 mi
Registration #3	2007-04-16	22.456 mi
Registration #4	2008-04-14	23.975 mi
Registration #5	2009-04-03	24.678 mi
Registration #6	2010-04-20	25.681 mi
Registration #7	2011-04-12	26.545 mi
Registration #8	2012-04-19	27.982 mi
Registration #9	2013-04-27	28.894 mi
Registration #10	2014-04-10	29.596 mi
Registration #11	2015-04-27	30.827 mi
Registration #12	2016-04-27	31.277 mi
Registration #13	2017-04-27	31.277 mi
Registration #14	2018-04-27	31.277 mi
Registration #15	2019-04-27	31.277 mi
Registration #16	2020-04-27	31.277 mi
Registration #17	2021-04-27	31.277 mi
Registration #18	2022-04-26	31.277 mi
Registration #19	2022-04-26	31.277 mi
Registration #20	2022-04-26	31.277 mi
Registration #21	2022-04-26	31.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1785 mm
Height	1710 mm
Length	4260 mm
Wheel base	2490 mm
Kerb weight	1385 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	1AZ0500609