



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	RAV-4 VVT-I XT5
Colour	Black
Year of manufacture	2005
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	147 BHP
Max. torque	192 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	211 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-09-26
Pictures	39
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-12
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	45
Total items failed	8

MOT #20 2023-09-25 13:46

MOT test number 423806622003

Result ✓ Passed

Next expiry date 2024-10-12

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated Drop link upper joint (5.3.4 (b) (i))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play Drop link bottom joint (5.3.4 (a) (i))

MOT #19 2022-09-29 15:51

MOT test number 440770536758

Result ✓ Passed

Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i))

Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Under trays fitted

MOT #18 2021-10-13 11:19

MOT test number 377700836773

Result ✓ Passed

**MOT #17** 2020-12-04 09:38**MOT test number** 445389998535**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Rear Nail in tyre Also perished**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**MOT #16** 2019-12-11 12:28**MOT test number** 323353269651**Result** ✓ Passed**MOT #15** 2018-12-21 11:34**MOT test number** 160062110122**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #14** 2017-12-19 11:39**MOT test number** 646352833495**Result** ✓ Passed**Advice** Front no plate damaged



MOT #13 2016-12-28 10:27

MOT test number 626970571148

Result ✓ Passed

- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened inner (3.5.1i)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened inner (3.5.1i)
- Advice** Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened inner (3.5.1i)

MOT #12 2016-12-06 13:39

MOT test number 258964826266

Result ✗ Failed

- Advice** Nearside Front Inner brake disc modified but not seriously weakened (3.5.1n)
- Fail** Central Exhaust has a major leak of exhaust gases (7.1.2)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Nearside Rear Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #11	2015-12-28 13:09
MOT test number	570658786570
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Advice	Offside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)
Advice	Brake pedal rubber worn
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Parking brake lever has little reserve travel (3.1.6b)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside rear exhaust tail pipe missing

MOT #10	2015-12-28 13:09
MOT test number	398733416257
Result	✗ Failed
Advice	Brake pedal rubber worn
Advice	Parking brake lever has little reserve travel (3.1.6b)
Advice	Offside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside rear exhaust tail pipe missing
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Pass with rectification	Offside Rear Stop lamp not working (1.2.1b)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #9** 2014-10-29 13:06**MOT test number** 358352004323**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Advice** Offside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**MOT #8** 2014-10-28 10:37**MOT test number** 225701304398**Result** ✗ Failed**Fail** Offside Inner Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Fail** Nearside Inner Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**MOT #7** 2013-11-01 09:15**MOT test number** 427255703418**Result** ✓ Passed**MOT #6** 2012-10-05 14:20**MOT test number** 746879372269**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2011-10-05 14:31**MOT test number** 959968071260**Result** ✓ Passed

**MOT #4** 2010-09-30 09:05**MOT test number** 324853070462**Result** ✓ Passed**Notice** Deep cut in nearside rear tyre tread**MOT #3** 2009-10-08 10:59**MOT test number** 524971089207**Result** ✓ Passed**MOT #2** 2008-10-07 10:24**MOT test number** 882211088293**Result** ✓ Passed**MOT #1** 2008-10-06 15:50**MOT test number** 340680788233**Result** ✗ Failed**Advice** Centre Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Offside Headlamp aim too high (1.8)**Advice** Offside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Nearside Headlamp aim too high (1.8)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
12 October 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	12 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	KV55HHK
Plate since	2019-03-28
Current registration	KV55HHK
Plate since	2019-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-09-22
Last registration	2023-09-25
Complete history	See info



Registration #1	2005-09-22	23 mi
Registration #2	2008-10-06	22.013 mi
Registration #3	2008-10-07	22.025 mi
Registration #4	2009-10-08	29.495 mi
Registration #5	2010-09-30	36.698 mi
Registration #6	2011-10-05	43.819 mi
Registration #7	2012-10-05	52.155 mi
Registration #8	2013-11-01	60.102 mi
Registration #9	2014-10-28	66.432 mi
Registration #10	2014-10-29	66.432 mi
Registration #11	2015-12-28	74.972 mi
Registration #12	2016-01-01	75.000 mi
Registration #13	2016-01-01	75.000 mi
Registration #14	2016-01-01	75.000 mi
Registration #15	2016-01-01	75.000 mi
Registration #16	2016-01-01	75.000 mi
Registration #17	2016-01-01	75.000 mi
Registration #18	2016-01-01	75.000 mi
Registration #19	2016-01-01	75.000 mi
Registration #20	2016-01-01	75.000 mi
Registration #21	2016-01-01	75.000 mi
Registration #22	2016-01-01	75.000 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1785 mm
Height	1710 mm
Length	4260 mm
Wheel base	2490 mm
Kerb weight	1385 kg
Max. allowed weight	1825 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1AZ1861813