





report date: 2024-03-29

General information

Make	VOLVO
Model	V60 D3 ES
Colour	Silver
Year of manufacture	2013
Top speed	127 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	350 Nm at 2.250 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-08-25

Pictures 26

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

Μ	OT	hist	ory

MOT expiry date	2025-02-01
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	6
Total items failed	3

MOT #10	2024-02-02 12:37
MOT test number	417786053481
Result	✓ Passed
Next expiry date	2025-02-01

MOT #9		2024-02-01 16:28
MOT test number	er	871174902782
Result		X Failed
DANGEROUS	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #8		2023-02-01 12:31
MOT test	number	995522305053
Result		✓ Passed
Advice	Nearside Rear Brake pad(s) wearing thin 2mm (1.1.13 (a) (ii))	
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #7	2022-01-12 09:24
MOT test number	494437137848
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #4

Fail

Fail

CX63BFP

report date: 2024-03-29

2019-01-11 11:02

MOT #6	2021-01-12 09:18
MOT test number	178202724733
Result	✓ Passed
MOT #5	2020-01-16 09:12
MOT test number	578368211993
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT test number	894184053910
Result	✓ Passed
MOT #3	2018-01-22 15:08
MOT test number	962271844160
Result	✓ Passed
MOT #2	2018-01-22 14:46
MOT test number	855481402281
Result	× Failed
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #1	2016-12-01 15:52
MOT test number	470381450057
Result	✓ Passed

Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Nearside Registration plate lamp not working (1.1.C.1d)

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	1 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



CX63BFP report date: 2024-03-29

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		
manage of the same		

	More info >	
Plate changes		
See in this check if this VOLVO had different number plates.		
Number of plates		,
Current registration	NK AIS UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 8/11



CX63BFP
report date: 2024-03-29

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-12-19
Last registration	2024-02-02
Complete history	See info



Registration #1	2013-12-19	18 mi
Registration #2	2016-12-01	63.331 mi
Registration #3	2018-01-22	76.076 mi
Registration #4	2018-01-22	76.076 mi
Registration #5	2019-01-11	86.306 mi
Registration #6	2020-01-16	100.419 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		71.777 es

More info >

CarCheck.co.uk page 10/11



CX63BFP report date: 2024-03-29

Car features

The VOLVO factory car options list is only available in the premium report. S0225 Air conditioning S0295 S0482 S0501 S0566 S0567 S0569 View the complete VOLVO factory list for this vehicle here. More info >

Safety ratings

NCAP rating	****
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1632 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	67 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/3