





General information

Make	JAGUAR
Model	S-TYPE V6 SE
Colour	Grey
Year of manufacture	2006
Top speed	145 mph
0 - 60 mph	7.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	299 Nm at 4.100 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Petrol
Consumption city	18.5 mpg
Consumption extra urban	35.3 mpg
Consumption combined	26.4 mpg
CO2 emission	259 g/km
CO2 label	Μ








Internet history

Entry 3	
Date	2021-09-10
Pictures	13
Listing price	View report



source: yesauto.com

Entry 2	
Date	2021-09-09
Pictures	14
Listing price	View report



source: cargurus.co.uk

Entry 1	
Date	2021-09-06
Pictures	20
Listing price	View report









source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-01
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	25
Total items failed	11

MOT #18		2024-02-02 17:33
MOT test	number	551244235032
Result		✓ Passed
Next expi	ry date	2025-02-01
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))	

MOT #17		2022-12-14 09:25
MOT test	number	635519339941
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

МОТ #16	2021-01-20 10:59
MOT test number	705805058015
Result	✓ Passed
Advice Rear subframe and body adjacent to forward mountings corroded	
Advice Both underfloor inner sills corroded but mostly hidden by plastic covers	
Minor Front All position lamps light intensity obviously reduced both flicker (4.2.3 (a) (i))





MOT #15	2021-01-12 16:15
MOT test number	818303711587
Result	🗙 Failed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge bald on inside edge	(5.2.3 (e))
Advice Nearside Front Tyre worn close to legal limit/worn on edge inside edge (5.2.3 (e))
Minor Front All position lamps light intensity obviously reduced both flicker (4.2.3 (a) ((i))
Fail Windscreen damaged and affecting the driver's view of an obligatory external min scratches and stone chip (3.2 (a) (ii))	ror multiple
Advice Both underfloor inner sills corroded but mostly hidden by plastic covers	
Advice Offside Rear Tyre worn close to legal limit/worn on edge bald on inside edge (5	5.2.3 (e))
Advice Offside Front Tyre worn close to legal limit/worn on edge and cracking in tread	(5.2.3 (e))
Fail Offside Headlamp aim too high (4.1.2 (a))	
Advice Rear subframe and body adjacent to forward mountings corroded	

MOT #14	2020-02-10 15:50
MOT test number	152946518678
Result	✓ Passed
MOT #13	2019-09-13 10:26

MOT test number	893983183729
Result	✓ Passed
MOT #12	2019-01-08 09:47
MOT test number	671101093967

Result

MOT #11	2018-03-21 13:27
MOT test number	528680488025
Result	✓ Passed

✓ Passed





MOT #2	10	2018-03-19 17:33
MOT te	st number	195346610094
Result		🗙 Failed
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail	Offside Rear Tyre has ply or cords exposed (4.1.D.1b)	
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail	Offside Front Tyre has ply or cords exposed (4.1.D.1b)	

МОТ #9	2017-02-01 11:55
MOT test number	517475475612
Result	✓ Passed
Advice Front Windscreen has damage to an area less than a 40mm cir	rcle outside zone 'A' (8.3.1d)

MOT #	8	2017-01-31 14:57
MOT te	st number	453118770299
Result		🗙 Failed
Advid	Front Windscreen has damage to an area less than a 40mm circle outside zone	'A' (8.3.1d)
Fail	Nearside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)	
Fail	Offside Front Headlamp aim too low (1.8)	
Fail	Parking brake: efficiency below requirements (3.7.B.7)	
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail	Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)	

MOT #7	2016-03-01 11:26
MOT test number	222986179161
Result	✓ Passed
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	





MOT #6	20	015-03-09 09:21
MOT test	number	329178365077
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
MOT #5	20	014-02-25 09:30
MOT test	number	758776554060
Result		✓ Passed
Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)		
Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)		
Notice Under-trays fitted obscuring some underside components		

MOT test number	295463063022
Result	✓ Passed
NoticeEngine covers fitted obscuring some components in the engine bayNoticeUnder-trays fitted obscuring some underside components	

MOT #3	2012-03-05 12:12
MOT test number	736745562034
Result	🗸 Passed
Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)	

MOT #2	2011-03-03 09:26
MOT test number	786592561078
Result	✓ Passed





MOT #1	2010-03-11 15:14
MOT test number	702170970029
Result	✓ Passed



Tax & MOT check

X Untaxed Tax expired: 10 April 2024	✓ MOT Expires: 1 February 2025
Tax status	Expired at 10 April 2024
Days left	20 days too late
MOT expiry date	1 February 2025
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	М
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-





Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
	E Store
Date	1. E
Category	amt
Туре	

Extra JAGUAR salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-12-20
Last registration	2024-02-02
Complete history	See info



Registration #1	2006-12-20	28 mi
Registration #2	2010-03-11	50.065 mi
Registration #3	2011-03-03	54.807 mi
Registration #4	2012-03-05	60.012 mi
Registration #5	2013-03-04	63.655 mi
Registration #6	2014-02-25	67.007 mi
Registration #7	2015-03-09	70.348 mi
Registration #8	2016-03-01	74.555 mi
Registration #9	2017-01-31	78.978 mi
Registration #10	2017-02-01	78.978 mi
Registration #11	2018-03-19	79.085 mi
Registration #12		11.777 esi
Registration #13		11.777 esi
Registration #14		11.777 est
Registration #15		11.777 esi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.117 esi
Registration #19		11.777 mi
Registration #20		11.117 est
Registration #21		11.777 mi
Registration #22		11.277 esi





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	2040 mm
Height	1444 mm
Length	4861 mm
Wheel base	2909 mm
Kerb weight	1710 kg
Max. allowed weight	2180 kg
Additional information	
Additional information Fuel tank capacity	69 I
	69 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 4