





report date: 2024-03-28

General information

Make	NISSAN
Model	PATHFINDER DCI TEKNA
Colour	Black
Year of manufacture	2011
Top speed	115 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	450 Nm at 2.000 rpm
Engine capacity	2.488 сс
Cylinders	4
Fuel type	Diesel
Consumption city	23.5 mpg
Consumption extra urban	38.7 mpg
Consumption combined	31.4 mpg
CO2 emission	238 g/km
CO2 label	L



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date	2022-11-14
Pictures	0

Listing price <u>View report</u>

source: carcraft.co.uk

Entry 1

Date	2022-07-24
Pictures	12
Listing price	View report









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-07-01
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	14
Total items failed	6

MOT #12		2023-06-28 16:20
MOT test	number	559864127580
Result		✓ Passed
Next expi	ry date	2024-07-01
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1	1.14 (a) (ii))
Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))		
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (2	1.1.14 (a) (ii))
Advice Vehicle structure is corroded but structural rigidity is not significantly reduced slight surface corrosion (6.1.1 (c) (i))		

MOT #11	2022-07-02 12:26
MOT test number	676367284548
Result	✓ Passed
MOT #10	2021-06-07 10:01
MOT test number	316569768072
Result	✓ Passed

MOT #9	2020-06-09 13:25
MOT test number	717238480365
Result	✓ Passed

CarCheck.co.uk page 3/12



 MOT #8
 2019-04-15 12:42

 MOT test number
 835829810143

 Result
 ✓ Passed

 MOT #7
 2018-04-20 14:20

 MOT test number
 559027279673

 Result
 ✓ Passed

 Advice
 Oil leak

MOT #6 2018-04-12 13:39 **MOT** test number 963286544171 × Failed Result **Advice** Oil leak Fail Offside Rear coil spring broken (2.4.C.1a) Fail Offside Headlamp cleaning device inoperative (1.7.2) Fail Exhaust emits an excessive level of metered smoke (7.4.B.3a) Fail Nearside Headlamp cleaning device inoperative (1.7.2)

MOT #5	2016-11-21 15:23
MOT test number	167083687938
Result	✓ Passed
MOT #4	2015-04-15 14:50
MOT test number	999435405127
Result	✓ Passed

CarCheck.co.uk page 4/12



MOT #3 2015-01-30 10:55

MOT test number 235940735064

Result
✓ Passed

Notice Oil leak

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)

MOT #2 2015-01-30 10:55

MOT test number 315730135095

Result X Failed

Pass with rectification Nearside Headlamp aim too high (1.8)

Advice Rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)

Pass with rectification Nearside Headlamp aim too low (1.8)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Oil leak

Advice Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2014-01-31 12:39

MOT test number 125581134422

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 November
Days left	187
MOT expiry date	1 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
manus .	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	OK ON THE OWNER OF THE OWNER OW
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-03-01
Last registration	2023-06-28
Complete history	See info



Registration #1	2011-03-01	11 mi
Registration #2	2014-01-31	42.132 mi
Registration #3	2015-01-30	70.040 mi
Registration #4	2015-04-15	70.830 mi
Registration #5	2016-11-21	80.162 mi
Registration #6	2018-04-12	84.989 mi
Registration #7	2018-04-20	85.094 mi
Registration #8		11.777 es
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		91,700 esi
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1848 mm
Height	1785 mm
Length	4813 mm
Wheel base	2853 mm
Kerb weight	2140 kg
Max. allowed weight	2880 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/1

Number of axles 2
Engine number 04319B