



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA HDI DESIRE 2 PICASSO
Colour	Green
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	205 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	61.4 mpg
Consumption combined	51.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-04-26
Pictures	23
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #19	2022-02-18 15:44
MOT test number	207088711440
Result	✓ Passed
Next expiry date	2023-02-17
Advice	Nearside Front and offside front outer sill soft

MOT #18	2022-02-04 10:47
MOT test number	887284792920
Result	✗ Failed
MAJOR	Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
MAJOR	Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
MAJOR	Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Nearside Front and offside front outer sill soft

MOT #17	2021-01-29 10:08
MOT test number	844231818777
Result	✓ Passed
Advice	Eml on
Advice	Underside of vehicle muddy
Advice	Rear Exhaust mounting defective (6.1.2 (a))
Advice	Front Lower outer sills getting soft

**MOT #16** 2021-01-23 09:15**MOT test number** 877692601329**Result** ✗ Failed

MAJOR Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))

Advice Front Lower outer sills getting soft

MAJOR Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Rear Exhaust mounting defective (6.1.2 (a))

Advice Eml on

Advice Underside of vehicle muddy

MAJOR Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #15 2020-01-24 07:36**MOT test number** 289056198130**Result** ✓ Passed**MOT #14** 2019-01-04 07:09**MOT test number** 134003519169**Result** ✓ Passed**MOT #13** 2017-09-11 04:47**MOT test number** 749453025768**Result** ✓ Passed**MOT #12** 2016-08-25 10:43**MOT test number** 777183736452**Result** ✓ Passed

**MOT #11** 2015-08-24 10:50**MOT test number** 327885962475**Result** ✓ Passed**MOT #10** 2014-08-28 12:29**MOT test number** 955930044205**Result** ✓ Passed**MOT #9** 2013-08-28 11:14**MOT test number** 277280143293**Result** ✓ Passed**MOT #8** 2013-08-28 11:14**MOT test number** 237390843229**Result** ✗ Failed**Pass with rectification** Offside Rear fog lamp not working (1.3.2b)**Pass with rectification** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #7** 2012-08-29 10:57**MOT test number** 929162742286**Result** ✓ Passed**MOT #6** 2012-08-29 10:57**MOT test number** 659362442261**Result** ✗ Failed**Pass with rectification** Offside Front Seat belt retracting mechanism defective (5.2.5b)**Pass with rectification** Offside Rear fog lamp not working (1.3.2b)**Pass with rectification** Rear registration plate insecure (6.3.1b)

**MOT #5** 2011-09-30 13:51**MOT test number** 616853471283**Result** ✓ Passed**MOT #4** 2011-09-29 14:45**MOT test number** 235362571255**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #3** 2010-07-07 12:09**MOT test number** 351068080162**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2009-07-07 11:28**MOT test number** 770818989197**Result** ✓ Passed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2008-07-03 10:19**MOT test number** 241395288459**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-07-30
Last registration	2022-02-18
Complete history	See info



Registration #1	2005-07-30	15 mi
Registration #2	2008-07-03	45.083 mi
Registration #3	2009-07-07	58.534 mi
Registration #4	2010-07-07	64.350 mi
Registration #5	2011-09-29	68.998 mi
Registration #6	2011-09-30	68.998 mi
Registration #7	2012-08-29	70.510 mi
Registration #8	2013-08-28	73.696 mi
Registration #9	2014-08-28	76.539 mi
Registration #10	2015-08-24	80.176 mi
Registration #11	2016-08-24	83.813 mi
Registration #12	2017-08-24	87.450 mi
Registration #13	2018-08-24	91.087 mi
Registration #14	2019-08-24	94.724 mi
Registration #15	2020-08-24	98.361 mi
Registration #16	2021-08-24	101.998 mi
Registration #17	2022-02-18	105.635 mi
Registration #18	2023-02-18	109.272 mi
Registration #19	2024-02-18	112.909 mi

More info >



Safety ratings

NCAP rating



Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1300 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	DYUF4010622