



AJ09ECE

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF S
Colour	Silver
Year of manufacture	-
Top speed	104 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	132 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg





Internet history

Entry 1

Date	2021-06-08
Pictures	10
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #17	2022-04-01 15:45
MOT test number	777528034964
Result	✓ Passed
Next expiry date	2023-03-31
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

MOT #16	2021-03-06 12:14
MOT test number	116113484698
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Nail in tyre
Advice	Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Advice	Reverse light not working

**MOT #15** 2021-03-06 09:41**MOT test number** 950823937514**Result** ✗ Failed**MAJOR** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Offside Rear Nail in tyre**Advice** Reverse light not working**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2020-03-14 10:12**MOT test number** 761463097393**Result** ✓ Passed**MOT #13** 2019-03-04 17:14**MOT test number** 594142585021**Result** ✓ Passed**MOT #12** 2019-03-01 15:50**MOT test number** 591999314017**Result** ✗ Failed**MAJOR** Front Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))**MAJOR** Emissions not tested (8.2.1.2 (d))**MAJOR** Offside Rear Direction indicator not working (4.4.1 (a) (ii))



MOT #11	2018-03-20 13:45
MOT test number	783522035667
Result	✓ Passed

MOT #10	2018-03-16 12:11
MOT test number	354476953974
Result	✗ Failed
Advice	Offside Front Tyre worn close to the legal limit And perished (4.1.E.1)
Advice	Oil sump corroded & leaking
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front Tyre worn close to the legal limit And perished (4.1.E.1)
Fail	Nearside Rear Mechanical brake component has restricted free movement (3.5.1k)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Front Shock absorber has a light misting of oil (2.7.3)
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #9	2017-08-08 13:13
MOT test number	354272877212
Result	✓ Passed
Advice	Nearside rear brake binding slightly
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside rear tyre worn on inner shoulder

**MOT #8** 2017-08-05 10:27**MOT test number** 500090180256**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside rear brake binding slightly**Fail** Nearside Front Front wheel bearing rough when rotated (2.5.A.2)**Advice** Nearside rear tyre worn on inner shoulder**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #7** 2016-07-13 09:23**MOT test number** 646884118925**Result** ✓ Passed**Advice** "bulb out " warning on dash possibly caused by offside rear stop tail bulb wrong wattage**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Tyre worn close to the legal limit oil leak from engine (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit 1956515 (4.1.E.1)**MOT #6** 2015-07-17 12:44**MOT test number** 247568795461**Result** ✓ Passed

**MOT #5** 2015-07-14 13:10**MOT test number** 529205795181**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Coil spring broken (2.4.C.1a)**Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2014-08-11 15:43**MOT test number** 556363724230**Result** ✓ Passed**MOT #3** 2014-08-11 10:33**MOT test number** 577393924285**Result** ✗ Failed**Fail** Nearside Side repeater not working (1.4.A.2c)**MOT #2** 2013-08-12 12:39**MOT test number** 336784823406**Result** ✓ Passed**Advice** Nearside Side repeater has light sources not illuminating, but not more than 50% (1.4.A.2c)**Notice** Slight cracking on rear tyre sidewalls**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Slight damage to rear bumper**MOT #1** 2012-07-20 13:28**MOT test number** 407282902275**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-06-01
Last registration	2022-04-01
Complete history	See info



Registration #1	2009-06-01	16 mi
Registration #2	2012-07-20	37.426 mi
Registration #3	2013-08-12	46.470 mi
Registration #4	2014-08-11	56.185 mi
Registration #5	2014-08-11	56.185 mi
Registration #6	2015-07-14	64.731 mi
Registration #7	2015-07-17	64.731 mi
Registration #8	2016-07-13	74.180 mi
Registration #9	2017-08-05	82.608 mi
Registration #10	2017-08-08	82.608 mi
Registration #11	2019-05-20	91.277 mi
Registration #12	2019-05-20	91.277 mi
Registration #13	2019-05-20	91.277 mi
Registration #14	2019-05-20	91.277 mi
Registration #15	2019-05-20	91.277 mi
Registration #16	2019-05-20	91.277 mi
Registration #17	2019-05-20	91.277 mi
Registration #18	2019-05-20	91.277 mi
Registration #19	2019-05-20	91.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1142 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	CGG 116680