





report date: 2024-03-29

### General information

Make	FIAT
Model	500L MULTIJET LOUNGE DUALOGIC
Colour	Red
Year of manufacture	2013
Top speed	102 mph
0 - 60 mph	15.1 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	85 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	76.4 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	В



CarCheck.co.uk page 1/13



report date: 2024-03-29

## Internet history

_				_	-
-	n	т	rv	,	

Liiti y I	
Date	2021-07-27
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-02-11
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	14
Total items failed	8

MOT #12	2024-01-18 10:35
MOT test number	698888743689
Result	✓ Passed
Next expiry date	2025-02-11
Advice Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))	


MOT #11		2024-01-18 10:35
MOT test number		682412322826
Result		<b>×</b> Failed
Pass with rectification	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Front Tyre worn	close to legal limit/worn on edge Both (5.2.3 (e))	

MOT #10	2023-02-01 11:18
MOT test number	722738664616
Result	✓ Passed
MOT #9	2022-02-03 10:33
MOT test number	214226862405
Result	<b>✓</b> Passed
Advice Offside Front Seat belt buckle slightly damaged (7.1.2 (d))	

CarCheck.co.uk page 3/13



report date: 2024-03-29



MOT #7		2021-02-12 17:49
MOT test	number	301355373963
Result		<b>✓</b> Passed
Advice	Manufactures under trays and engine covers on vehicle	
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Front spoiler insecure	
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #6	2021-02-10 16:19
MOT test number	685863207867
Result	🗙 Failed
Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Fail Nearside Front Anti-roll bar ball joint likely to become detached (5.3.4 (a) (ii))	
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Front spoiler insecure	
Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Fail Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Manufactures under trays and engine covers on vehicle	

MOT #5	2019-04-26 14:50
MOT test number	931034100858
Result	<b>✓</b> Passed
MOT #4	2018-08-01 14:12
MOT test number	160912757202
Result	✓ Passed
MOT #3	2017-08-22 12:14
MOT test number	708741911754
Result	✓ Passed
MOT #2	2016-09-16 14:26
MOT test number	835312438490
Result	✓ Passed

CarCheck.co.uk page 5/13



MOT #1 2016-09-16 12:20

**MOT test number** 647954993220

## Result



**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

CarCheck.co.uk page 6/13



report date: 2024-03-29

### Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	11 February 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 7/13




report date: 2024-03-29

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Plate since

FE63KRK

report date: 2024-03-29

Owner history		
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report $\underline{\mathbf{k}}$		?
*******		
***************************************		
************		
********		
***************************************		
THE STREET		
	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		
Current registration	UK NEK	
Plate since		

More info >

UK UK

CarCheck.co.uk page 10/13



report date: 2024-03-29

#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-09-25
Last registration	2024-01-18
Complete history	See info



Registration #1	2013-09-25	23 mi
Registration #2	2016-09-16	26.699 mi
Registration #3	2016-09-16	26.699 mi
Registration #4	2017-08-22	37.663 mi
Registration #5	2018-08-01	47.053 mi
Registration #6	2019-04-26	54.865 mi
Registration #7	2021-02-10	60.298 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	94%
Children	78%
Pedestrian	65%
Safety systems	71%
Overall rating	83%
Video	see crash video



## Dimensions & weight

Width	2018 mm
Height	1667 mm
Length	4147 mm
Wheel base	2612 mm
Kerb weight	1320 kg
Max. allowed weight	1880 kg

# Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/1

Number of axles 2

Engine number 4939266