





report date: 2024-03-29

General information

Make	FIAT
Model	GRANDE PUNTO SOUND
Colour	Grey
Year of manufacture	2010
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/13



PK60KHU report date: 2024-03-29

Internet history

Entry 1

Date 2022-01-14

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MC	TC	history	
----	----	---------	--

MOT expiry date	2025-02-10
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	16
Total items failed	7

MOT #15	2024-01-26 16:01
MOT test number	689793329855
Result	✓ Passed
Next expiry date	2025-02-10

MOT #14	2024-01-25 14:01
MOT test number	918594706562
Result	X Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Front Tyre tread depth below requirements of 1.6mm worn on inner e	dge (5.2.3 (e))

MOT #13		2023-02-11 11:24
MOT test	number	407224443077
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Suspension components corroded	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #12 2023-01-31 13:48

MOT test number 254169387508

Result X Failed

Fail Nearside Front Suspension arm corroded and seriously weakened (5.3.3 (b) (i))

Advice Suspension components corroded

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail Nearside Headlamp has a product on the light source so that the light output is severely reduced (4.1.4 (b))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #11 2021-11-24 15:59

MOT test number 423322719564

Result ✓ Passed

MOT #10 2021-11-24 12:25

MOT test number 260847906408

Result X Failed

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Emissions not tested (8.2.1.2 (d))

MOT #9 2020-11-02 11:19

MOT test number 520874939667

Result / Passed

Advice Rear tyres perished

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #8 2019-11-18 09:56

MOT test number 875631672809

MOT #7 2018-11-19 14:07

MOT test number 457451183358

Result
✓ Passed

Advice Rear shock absorbers heavily corroded but not leaking

Advice Rear exhaust silencer corroded

MOT #6 2018-11-19 10:03

MOT test number 433966662841

Result X Failed

Advice Rear exhaust silencer corroded

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Rear shock absorbers heavily corroded but not leaking

MOT #5 2017-11-27 10:27

MOT test number 112288426086

Result

Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #4 2016-11-28 09:47

MOT test number 861089325648

Result
✓ Passed

MOT #3 2015-11-26 10:25

MOT test number 948506785970

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 5/13



PK60KHU report date: 2024-03-29

MOT #2	2014-11-03 09:27
MOT test number	596307704368
Result	✓ Passed
MOT #1	2013-11-18 09:36
MOT test number	409102623353
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	10 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

_	
Owner	history
OWILL	1113601

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report h	

THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	UK NEC
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-11-30
Last registration	2024-01-26
Complete history	See info



Registration #1	2010-11-30	25 mi
Registration #2	2013-11-18	15.845 mi
Registration #3	2014-11-03	17.619 mi
Registration #4	2015-11-26	21.225 mi
Registration #5	2016-11-28	26.518 mi
Registration #6	2017-11-27	32.077 mi
Registration #7	2018-11-19	37.445 mi
Registration #8	2018-11-19	37.445 mi
Registration #9	2019-11-18	42.116 mi
Registration #9	2019-11-10	42.110 1111
Registration #10	2019-11-10	42.110 IIII
	2019-11-10	42.110 IIII
Registration #10	2019-11-10	42.110 IIII
Registration #10 Registration #11	2019-11-10	42.110 IIII
Registration #10 Registration #11 Registration #12	2019-11-10	42.110 IIII
Registration #10 Registration #11 Registration #12 Registration #13	2019-11-10	42.110 1111
Registration #10 Registration #11 Registration #12 Registration #13 Registration #14	2019-11-10	42.110 1111

More info >

CarCheck.co.uk page 12/13



PK60KHU report date: 2024-03-29

Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13