



MW18EYD

report date: 2024-03-28

General information

|                     |                                         |
|---------------------|-----------------------------------------|
| Make                | BMW                                     |
| Model               | 2 SERIES 220D XDRIVE LUXURY GRAN TOURER |
| Colour              | Silver                                  |
| Year of manufacture | 2018                                    |
| Top speed           | 138 mph                                 |
| 0 - 60 mph          | 8.0 seconds                             |
| Gearbox             | 8 speed automatic                       |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 188 BHP             |
| Max. torque             | 400 Nm at 1.750 rpm |
| Engine capacity         | 1.995 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 53.3 mpg            |
| Consumption extra urban | 64.2 mpg            |
| Consumption combined    | 60.1 mpg            |
| CO2 emission            | 129 g/km            |
| CO2 label               | D                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-08-31                  |
| Pictures      | 17                          |
| Listing price | <a href="#">View report</a> |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2025-04-22 |
| MOT pass rate      | 67 %       |
| MOT passed         | 4          |
| Failed MOT tests   | 2          |
| Total advice items | 15         |
| Total items failed | 5          |

|                  |                                                                                  |
|------------------|----------------------------------------------------------------------------------|
| MOT #6           | 2024-04-15 10:48                                                                 |
| MOT test number  | 756462200349                                                                     |
| Result           | ✓ Passed                                                                         |
| Next expiry date | 2025-04-22                                                                       |
| Advice           | Nearside Front Tyre worn close to legal limit/worn on edge Tread 2mm (5.2.3 (e)) |
| Advice           | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))            |

|                         |                                                                                  |
|-------------------------|----------------------------------------------------------------------------------|
| MOT #5                  | 2024-04-15 10:48                                                                 |
| MOT test number         | 111000407657                                                                     |
| Result                  | ✗ Failed                                                                         |
| Pass with rectification | Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))                          |
| Advice                  | Nearside Front Tyre worn close to legal limit/worn on edge Tread 2mm (5.2.3 (e)) |
| Advice                  | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))            |

|                 |                  |
|-----------------|------------------|
| MOT #4          | 2023-04-05 10:34 |
| MOT test number | 194533599806     |
| Result          | ✓ Passed         |

**MOT #3**

2022-04-22 14:02

**MOT test number**

690396121153

**Result**

✓ Passed

**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Tread 2mm (5.2.3 (e))**Advice** Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2**

2021-04-23 15:05

**MOT test number**

907500083145

**Result**

✓ Passed

**Advice** Front washers poor**Advice** Rear brake pads getting low**MOT #1**

2021-04-23 11:51

**MOT test number**

779803651178

**Result**

✗ Failed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge side wall cut (5.2.3 (e))**Fail** Nearside Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**Fail** Nearside Front Windscreen washer not working (3.5 (a))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge side wall cuts (5.2.3 (e))**Fail** Offside Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**Fail** Offside Front Windscreen washer not working (3.5 (a))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear brake pads getting low



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
22 April 2025

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 March             |
| <b>Days left</b>        | 305                             |
| <b>MOT expiry date</b>  | 22 April 2025                   |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|                                                             |            |
|-------------------------------------------------------------|------------|
| <b>Vehicle class</b>                                        | 49         |
| <b>Band</b>                                                 | G          |
| <b>First licence fee (12 months)</b>                        | £ 210,00,- |
| <b>First licence fee diesel non RDE2 tested (12 months)</b> | £ 255,00,- |
| <b>Standard rate (12 months)</b>                            | £ 180,00,- |
| <b>Standard rate (6 months)</b>                             | £ 99,00,-  |
| <b>Premium rate (12 months)</b>                             | £ 570,00,- |
| <b>Premium rate (6 months)</b>                              | £ 313,50,- |



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

|          |  |
|----------|--|
| Damage 1 |  |
| Date     |  |
| Category |  |
| Type     |  |
| Damage 2 |  |
| Date     |  |
| Category |  |
| Type     |  |



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this BMW had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 0          |
| Current registration |            |
| Plate since          | 2019-09-29 |
| Current registration |            |
| Plate since          | 2019-09-29 |

More info >





Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

|                   |          |          |
|-------------------|----------|----------|
| Finance company   | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type    | REDACTED | REDACTED |
| Agreement term    | REDACTED | REDACTED |
| Agreement number  | REDACTED | REDACTED |
| Contact info      | REDACTED | REDACTED |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 8                        |
| First mileage registration | 2018-05-30               |
| Last registration          | 2024-04-15               |
| Complete history           | <a href="#">See info</a> |



|                 |            |           |
|-----------------|------------|-----------|
| Registration #1 | 2018-05-30 | 17 mi     |
| Registration #2 | 2021-04-23 | 39.284 mi |
| Registration #3 | 2021-04-23 | 39.284 mi |
| Registration #4 | 2022-05-20 | 39.284 mi |
| Registration #5 | 2022-05-20 | 39.284 mi |
| Registration #6 | 2022-05-20 | 39.284 mi |
| Registration #7 | 2022-05-20 | 39.284 mi |
| Registration #8 | 2022-05-20 | 39.284 mi |

More info >



Car features

The BMW factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 87%                             |
| Children       | 86%                             |
| Pedestrian     | 64%                             |
| Safety systems | 71%                             |
| Overall rating | 81%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1800 mm |
| Height              | 1586 mm |
| Length              | 4342 mm |
| Wheel base          | 2780 mm |
| Kerb weight         | 1665 kg |
| Max. allowed weight | 2375 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 51 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 7                |

|                 |          |
|-----------------|----------|
| Number of axles | 2        |
| Engine number   | 69165415 |