



RENAULT

FA08GKO


report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE VVT 111 EU4
Colour	Grey
Year of manufacture	2008
Top speed	121 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	148 Nm at 3.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	164 g/km
CO2 label	G





## MOT history

MOT expiry date	2021-03-11
MOT pass rate	56 %
MOT passed	9
Failed MOT tests	7
Total advice items	23
Total items failed	20

MOT #16	2020-03-12 16:54
MOT test number	351002670064
Result	✓ Passed
Next expiry date	2021-03-11

MOT #15	2020-01-19 12:50
MOT test number	209029415341
Result	✗ Failed
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Advice	Nearside Front Non obligatory mirror damaged
Fail	Oil leaking excessively from engine (8.4.1 (a) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14	2019-01-16 15:34
MOT test number	178904674965
Result	✓ Passed

**MOT #13** 2019-01-11 15:54**MOT test number** 259303939573**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Fail** Nearside Front All position lamps not working (4.2.1 (a))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #12** 2017-11-07 15:10**MOT test number** 876154545720**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2017-11-07 15:10**MOT test number** 210509812679**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2016-10-31 16:23**MOT test number** 324299835801**Result** ✓ Passed

**MOT #9** 2016-10-29 09:52**MOT test number** 414839714245**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front Suspension arm has excessive play in a pin/bush rear bush (2.4.G.2)**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**MOT #8** 2015-07-29 15:36**MOT test number** 309050315279**Result** ✓ Passed**MOT #7** 2014-06-13 11:28**MOT test number** 959834264183**Result** ✓ Passed**MOT #6** 2013-05-24 15:38**MOT test number** 175454643159**Result** ✓ Passed**MOT #5** 2013-05-24 15:38**MOT test number** 206644443111**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)



<b>MOT #4</b>	2012-04-30 15:35
<b>MOT test number</b>	678241722131
<b>Result</b>	✓ Passed
<b>Notice</b>	Belly panel fitted
<b>Notice</b>	Child seat fitted not allowing full inspection of adult belt

<b>MOT #3</b>	2012-04-27 14:57
<b>MOT test number</b>	179918612134
<b>Result</b>	✗ Failed
<b>Notice</b>	Child seat fitted not allowing full inspection of adult belt
<b>Fail</b>	Nearside Front position lamp(s) not working (1.1.A.3b)
<b>Fail</b>	Offside Rear wheel bearing has excessive play (2.6.2)
<b>Notice</b>	Belly panel fitted
<b>Fail</b>	Offside Stop lamp not working (1.2.1b)
<b>Fail</b>	Nearside Rear wheel bearing has excessive play (2.6.2)

<b>MOT #2</b>	2011-04-06 16:53
<b>MOT test number</b>	137186191005
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
<b>Notice</b>	Air bag light on
<b>Advice</b>	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Nearside Rear wheel bearing has slight play (2.6.2)
<b>Notice</b>	Under tray fitted
<b>Advice</b>	Front Brake pad(s) wearing thin (3.5.1g)



MOT #12011-04-04 16:46

MOT test number969884991076

Result

Failed

- Fail

Nearside Rear Registration plate lamp not working (1.1.C.1d)
- Advice

Front Brake pad(s) wearing thin (3.5.1g)
- Notice

Air bag light on
- Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail

Offside Rear Registration plate lamp not working (1.1.C.1d)
- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice

Under tray fitted
- Advice

Nearside Rear wheel bearing has slight play (2.6.2)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-05-02
Last registration	2020-03-12
Complete history	<a href="#">See info</a>



Registration #1	2008-05-02	25 mi
Registration #2	2011-04-04	29.263 mi
Registration #3	2011-04-06	29.397 mi
Registration #4	2012-04-27	44.858 mi
Registration #5	2012-04-30	44.878 mi
Registration #6	2013-05-24	53.052 mi
Registration #7	2014-06-13	61.021 mi
Registration #8	2015-07-29	69.363 mi
Registration #9	2016-08-01	75.377 mi
Registration #10	2017-08-01	81.391 mi
Registration #11	2018-08-01	87.405 mi
Registration #12	2019-08-01	93.419 mi
Registration #13	2020-03-12	99.433 mi
Registration #14	2020-03-12	99.433 mi
Registration #15	2020-03-12	99.433 mi
Registration #16	2020-03-12	99.433 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1699 mm
Height	1420 mm
Length	4129 mm
Wheel base	2625 mm
Kerb weight	1175 kg
Max. allowed weight	1725 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D167628