



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO SPORT TDI (100BHP)
Colour	Silver
Year of manufacture	2007
Top speed	117 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	240 Nm at 1.800 rpm
Engine capacity	1.900 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	68.9 mpg
Consumption combined	56.5 mpg
CO2 emission	129 g/km
CO2 label	D





## MOT history

MOT expiry date	2020-08-16
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	7
Total items failed	5

MOT #15 2019-08-17 09:59

MOT test number 124295925331

Result ✓ Passed

Next expiry date 2020-08-16

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #14 2018-08-14 13:39

MOT test number 126098115728

Result ✓ Passed

MOT #13 2018-08-14 13:39

MOT test number 514957770836

Result ✗ Failed

- Pass with rectification** Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Pass with rectification** Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Pass with rectification** Offside Front Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #12** 2017-10-31 11:23**MOT test number** 490171858104**Result** ✓ Passed**MOT #11** 2016-10-28 10:43**MOT test number** 324689955825**Result** ✓ Passed**MOT #10** 2015-11-06 10:59**MOT test number** 280929895260**Result** ✓ Passed**MOT #9** 2015-11-05 11:36**MOT test number** 206772849401**Result** ✗ Failed**Fail** Nearside Front Seat belt damaged sufficient to significantly weakened the webbing (5.2.2a)**MOT #8** 2014-10-21 14:51**MOT test number** 587234194221**Result** ✓ Passed**MOT #7** 2014-10-21 11:50**MOT test number** 738584194298**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #6** 2013-11-05 08:58**MOT test number** 776229703379**Result** ✓ Passed



<b>MOT #5</b>	2012-11-05 09:37
---------------	------------------

<b>MOT test number</b>	469180212364
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2012-09-04 15:30
---------------	------------------

<b>MOT test number</b>	299858242243
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2011-10-10 11:49
---------------	------------------

<b>MOT test number</b>	557963181252
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Notice</b>	Rear tyres deteriorated
---------------	-------------------------

<b>MOT #2</b>	2010-10-20 14:00
---------------	------------------

<b>MOT test number</b>	861013290277
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2009-10-19 14:51
---------------	------------------

<b>MOT test number</b>	512122299238
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Notice</b>	Cuts in both front tyres not reach cords or ply
---------------	---



Tax & MOT check

X

Untaxed

Tax expired:  
5 July 2020

X

MOT

Expired:  
16 August 2020

Tax status	Expired at 5 July 2020
Days left	1393 days too late
MOT expiry date	16 August 2020
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>KR56PNO</b>
Plate since	2019-06-29
Current registration	 <b>KR56PNO</b>
Plate since	2019-06-29

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-02-21
Last registration	2019-08-17
Complete history	<a href="#">See info</a>



Registration #1	2007-02-21	15 mi
Registration #2	2009-10-19	26.073 mi
Registration #3	2010-10-20	41.415 mi
Registration #4	2011-10-10	52.265 mi
Registration #5	2012-09-04	61.228 mi
Registration #6	2012-11-05	61.250 mi
Registration #7	2013-11-05	69.510 mi
Registration #8	2014-10-21	75.863 mi
Registration #9	2015-05-20	85.277 mi
Registration #10	2015-05-20	95.277 mi
Registration #11	2015-05-20	105.277 mi
Registration #12	2015-05-20	115.277 mi
Registration #13	2015-05-20	125.277 mi
Registration #14	2015-05-20	135.277 mi
Registration #15	2015-05-20	145.277 mi
Registration #16	2015-05-20	155.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Kerb weight	1300 kg
Max. allowed weight	1680 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	AXR534266