



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM BLUE DRIVE
Colour	Silver
Year of manufacture	2016
Top speed	126 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	197 BHP
Max. torque	440 Nm at 2.750 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	46.3 mpg
Consumption combined	42.2 mpg
CO2 emission	174 g/km
CO2 label	H






Internet history

Entry 2

Date	2022-05-31
Pictures	44
Listing price	View report



source: yesauto.com

Entry 1

Date	2021-10-26
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-22
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	12
Total items failed	1

MOT #8 2023-05-19 10:19

MOT test number 706042847671

Result ✓ Passed

Next expiry date 2024-05-22

Advice Offside Front Tyre worn close to legal limit/worn on edge worn to 2.mm and worn smooth almost to cords on inner edges (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn to 2.mm and worn smooth on inner edges (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge worn on inner edges (5.2.3 (e))

MOT #7 2022-05-23 10:56

MOT test number 450473607134

Result ✓ Passed

MOT #6 2021-12-07 09:08

MOT test number 567965177678

Result ✓ Passed

MOT #5 2021-08-26 14:14

MOT test number 662643623156

Result ✓ Passed

**MOT #4** 2021-08-25 15:42**MOT test number** 212845975186**Result** ✗ Failed**Fail** Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #3** 2021-02-19 11:56**MOT test number** 878756047419**Result** ✓ Passed**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))**MOT #2** 2020-02-05 11:52**MOT test number** 974744576818**Result** ✓ Passed**Advice** Front Both front brake discs have slight corrosion outer edges**MOT #1** 2019-02-26 09:22**MOT test number** 475691123224**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Emissions too clean to record**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓
Taxed

Tax due:
1 May 2024

✓
MOT

Expires:
22 May 2024

Tax status	Valid until 1 May
Days left	2
MOT expiry date	22 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	VX16XNF
Plate since	2019-09-28
Current registration	VX16XNF
Plate since	2019-09-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-03-30
Last registration	2023-05-19
Complete history	See info



Registration #1	2016-03-30	15 mi
Registration #2	2019-02-26	27.421 mi
Registration #3	2020-02-05	30.124 mi
Registration #4	2021-02-19	32.555 mi
Registration #5	2021-08-25	34.452 mi
Registration #6	2021-08-26	34.452 mi
Registration #7	2023-05-19	35.277 mi
Registration #8	2023-05-19	35.277 mi
Registration #9	2023-05-19	35.277 mi
Registration #10	2023-05-19	35.277 mi
Registration #11	2023-05-19	35.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	89%
Pedestrian	71%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1880 mm
Height	1675 mm
Length	4700 mm
Wheel base	2700 mm
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

D4HBGU447369