



report date: 2024-03-28

General information

Make	MINI
Model	JOHN COOPER WORKS
Colour	Grey
Year of manufacture	2010
Top speed	148 mph
0 - 60 mph	6.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	211 BHP
Max. torque	260 Nm at 5.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg
CO2 emission	165 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-02
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2024-11-22
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	14
Total items failed	14

MOT #16	2023-11-23 08:57
MOT test number	299499347095
Result	✓ Passed
Next expiry date	2024-11-22

MOT #15	2023-11-14 13:28
MOT test number	779309550207
Result	✗ Failed
Fail	Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14	2022-10-21 08:46
MOT test number	937158118577
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened poor condition on braking surfaces (1.1.14 (a) (ii))

**MOT #13**

2022-10-20 08:19

**MOT test number**

972076850066

**Result****✗ Failed****Advice** Offside Front Tyre worn close to legal limit/worn on edge on legal limit (205/45/ZR17 W) (5.2.3 (e))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened poor condition on inner braking surfaces (1.1.14 (a) (ii))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure inner sidewall (5.2.3 (d) (ii))**Advice** Front brake wear sensor broken**Advice** Nearside Front Tyre worn close to legal limit/worn on edge on legal limit (5.2.3 (e))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened poor condition on braking surfaces (1.1.14 (a) (ii))**Fail** Oil leaking excessively from engine (8.4.1 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure inner sidewall (5.2.3 (d) (ii))**MOT #12**

2021-11-15 12:25

**MOT test number**

144973851352

**Result****✓ Passed****MOT #11**

2020-11-19 16:43

**MOT test number**

906474768700

**Result****✓ Passed****Advice** Engine oil leak

**MOT #10** 2020-11-19 10:25**MOT test number** 102460945326**Result** ✗ Failed**Advice** Engine oil leak**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #9** 2020-11-17 17:39**MOT test number** 174472072660**Result** ✗ Failed**Fail** Oil leaking continuously from engine posing a serious risk to road safety low level (8.4.1 (a) (ii))**Fail** Offside Rear Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2019-11-11 10:27**MOT test number** 436329872963**Result** ✓ Passed**MOT #7** 2019-02-11 17:00**MOT test number** 706122686873**Result** ✓ Passed**MOT #6** 2017-09-26 16:25**MOT test number** 511154541955**Result** ✓ Passed**Advice** Rear tyres wearing on inner tread**Advice** Items removed from driver's view prior to test

**MOT #5** 2015-09-18 13:54**MOT test number** 974691389941**Result** ✓ Passed**MOT #4** 2014-09-29 15:33**MOT test number** 336082074489**Result** ✓ Passed**MOT #3** 2014-09-29 15:33**MOT test number** 316362274482**Result** ✗ Failed**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**MOT #2** 2013-09-26 13:03**MOT test number** 999099563234**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Front Headlamp aim too high (1.8)**MOT #1** 2013-09-26 13:03**MOT test number** 518929263287**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
22 November 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	217
<b>MOT expiry date</b>	22 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-09-29
Current registration	 *****
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-10-01
Last registration	2023-11-23
Complete history	<a href="#">See info</a>



Registration #1	2010-10-01	22 mi
Registration #2	2013-09-26	8.886 mi
Registration #3	2014-09-29	13.715 mi
Registration #4	2015-09-18	16.305 mi
Registration #5	2017-09-26	18.294 mi
Registration #6	2019-02-11	19.178 mi
Registration #7	2019-11-11	21.288 mi
Registration #8	2020-11-17	31.104 mi
Registration #9	2020-11-17	31.104 mi
Registration #10	2020-11-17	31.104 mi
Registration #11	2020-11-17	31.104 mi
Registration #12	2020-11-17	31.104 mi
Registration #13	2020-11-17	31.104 mi
Registration #14	2020-11-17	31.104 mi
Registration #15	2020-11-17	31.104 mi
Registration #16	2020-11-17	31.104 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1913 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1130 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Engine number	B3811718
---------------	----------