




report date: 2024-03-29

General information

Make	FIAT
Model	TIPO MULTIJET LOUNGE
Colour	Silver
Year of manufacture	2017
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	99 g/km
CO2 label	A







Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-13
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	17
Total items failed	0

MOT #7 2024-02-14 15:40

MOT test number 686712607368

Result ✓ Passed

Next expiry date 2025-02-13

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2024-02-14 09:29

MOT test number 263627702429

Result ✗ Failed

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- DANGEROUS** Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2023-02-08 12:16

MOT test number 478794961456

Result ✓ Passed

- Advice** Engine oil level low
- Advice** Nearside Rear Outer Sill damaged
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #4	2023-02-08 11:49
MOT test number	371932288340
Result	✗ Failed
Advice	Engine oil level low
MAJOR	Nearside Front Side repeater not working (4.4.1 (a) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Outer Sill damaged

MOT #3	2022-01-13 09:52
MOT test number	563241154582
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge starting to wear on inner edge of tread (5.2.3 (e))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge starting to wear on inner edge of tread (5.2.3 (e))
Advice	T.p.m.s light on

MOT #2	2020-12-16 09:20
MOT test number	195020985360
Result	✓ Passed

MOT #1	2020-03-02 13:28
MOT test number	985493225685
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 February 2025

✓
MOT

Expires:
13 February 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	13 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	WN17CFE
Plate since	2024-03-29
Current registration	WN17CFE
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-03-03
Last registration	2024-02-14
Complete history	See info



Registration #1	2017-03-03	22 mi
Registration #2	2020-03-02	29.341 mi
Registration #3	2020-12-16	33.229 mi
Registration #4	[blurred]	[blurred]
Registration #5	2022-01-13	40.632 mi
Registration #6	[blurred]	[blurred]
Registration #7	[blurred]	[blurred]
Registration #8	[blurred]	[blurred]
Registration #9	[blurred]	[blurred]

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	82%
Children	60%
Pedestrian	62%
Safety systems	57%
Overall rating	68%
Video	see crash video



Copyright © 2016 Euro NCAP

Dimensions & weight

Width	1792 mm
Height	1495 mm
Length	4368 mm
Wheel base	2638 mm
Kerb weight	1365 kg
Max. allowed weight	1790 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	6330844