




report date: 2024-03-28

General information

Make	VOLVO
Model	C30 SE LUX
Colour	Grey
Year of manufacture	2009
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I






Internet history

Entry 1

Date	2022-04-29
Pictures	17
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-22
MOT pass rate	100 %
MOT passed	12
Failed MOT tests	0
Total advice items	13
Total items failed	0

MOT #12	2023-06-23 10:48
MOT test number	532275552112
Result	✓ Passed
Next expiry date	2024-06-22

MOT #11	2022-06-16 14:51
MOT test number	590537705014
Result	✓ Passed

MOT #10	2021-11-24 13:32
MOT test number	799628259278
Result	✓ Passed
Advice	Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #9** 2020-11-30 13:56**MOT test number** 683991021250**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #8** 2019-12-04 13:46**MOT test number** 510530818113**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2018-12-05 15:37**MOT test number** 840066194114**Result** ✓ Passed**MOT #6** 2017-12-04 12:22**MOT test number** 489432770237**Result** ✓ Passed**Advice** Light misting of oil around O/S driveshaft oil seal**Advice** Age related cracking in N/S/R outer sidewall**MOT #5** 2016-12-02 13:53**MOT test number** 873138289047**Result** ✓ Passed



<b>MOT #4</b>	2015-11-19 14:08
---------------	------------------

<b>MOT test number</b>	996837644084
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Deep cuts in nearside front tyre sidewall, no cords
---------------	---

<b>MOT #3</b>	2014-11-12 10:56
---------------	------------------

<b>MOT test number</b>	329516714352
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2013-11-13 11:08
---------------	------------------

<b>MOT test number</b>	395157313313
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2012-11-14 11:15
---------------	------------------

<b>MOT test number</b>	289919112389
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Notice</b>	CUT IN N/S FRONT TYRE OUTER SIDEWALL NOT TO CHORDS
---------------	--

<b>Notice</b>	SMALL CHIPS IN WINDSCREEN
---------------	---------------------------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
22 June 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	22 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-12-05
Last registration	2023-06-23
Complete history	<a href="#">See info</a>



Registration #1	2009-12-05	17 mi
Registration #2	2012-11-14	15.144 mi
Registration #3	2013-11-13	20.103 mi
Registration #4	2014-11-12	24.977 mi
Registration #5	2015-11-19	29.704 mi
Registration #6	2016-12-02	34.748 mi
Registration #7	2017-12-04	39.029 mi
Registration #8	2018-06-20	43.277 mi
Registration #9	2019-06-20	47.525 mi
Registration #10	2020-06-20	51.773 mi
Registration #11	2021-06-20	56.021 mi
Registration #12	2022-06-20	60.269 mi
Registration #13	2023-06-23	64.517 mi
Registration #14	2024-03-28	68.765 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1344 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	175195