



report date: 2024-03-29

General information

Make	LAND ROVER
Model	FREELANDER SD4 HSE LUXURY
Colour	Black
Year of manufacture	2013
Top speed	118 mph
0 - 100 km/h	11.2 seconds
0 - 60 mph	8.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	110 kW / 150 HP / 190 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-12-24
Pictures	13
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-02
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	36
Total items failed	9

MOT #10	2023-12-01 11:06
MOT test number	767070674080
Result	✓ Passed
Next expiry date	2024-12-02
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2022-11-25 13:27
MOT test number	694340016504
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8**

2022-11-24 13:15

MOT test number

915539142944

Result**✗ Failed**

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #7

2021-12-03 16:10

MOT test number

895416368255

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6**

2021-11-23 17:18

MOT test number

773343901353

Result

✗ Failed

- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

MOT #5

2020-11-06 11:40

MOT test number

348372670109

Result

✓ Passed

- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Unable to fully inspect due to covers and shields
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Central Rear Upper Stop lamp(s) non-obligatory stop lamp not working high level brake light not working (4.3.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge slightly worn (5.2.3 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #4

2019-10-25 12:12

MOT test number

885180537030

Result

✓ Passed

- Advice** Unable to fully inspect due to covers and shields
- Advice** Slight play Off side trackrod end

**MOT #3** 2018-10-15 08:20**MOT test number** 547874500729**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Unable to fully inspect due to covers and shields
- Advice** Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

MOT #2 2018-10-15 08:20**MOT test number** 395960318547**Result** ✗ Failed

- Pass with rectification** Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Unable to fully inspect due to covers and shields

MOT #1 2016-11-12 12:40**MOT test number** 151332804135**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
2 December 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	2 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	GU63YUX
Plate since	2019-03-29
Current registration	GU63YUX
Plate since	2019-03-29

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-10-25
Last registration	2023-12-01
Complete history	See info



Registration #1	2013-10-25	20 mi
Registration #2	2016-11-12	26.055 mi
Registration #3	2018-10-15	62.845 mi
Registration #4	2018-10-15	62.845 mi
Registration #5	2019-10-25	82.667 mi
Registration #6	2020-11-06	93.160 mi
Registration #7	2023-12-01	93.160 mi
Registration #8	2023-12-01	93.160 mi
Registration #9	2023-12-01	93.160 mi
Registration #10	2023-12-01	93.160 mi
Registration #11	2023-12-01	93.160 mi
Registration #12	2023-12-01	93.160 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	2180 mm
Height	1740 mm
Length	4500 mm
Wheel base	2660 mm
Kerb weight	1770 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DZ784152302224DT