





report date: 2024-03-28

General information

Make	AUDI
Model	Q3 TDI QUATTRO S LINE
Colour	Blue
Year of manufacture	2014
Top speed	132 mph
0 - 100 km/h	8.2 seconds
0 - 60 mph	8.2 seconds
Gearbox	7 speed Semi-Automatic

Engine & fuel consumption

Power	130 kW / 177 HP / 174 BHP
Max. torque	380 Nm at 1.750 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date	2021-07-08	
Pictures	1	
Listing price	View report	



source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-12-14
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	11
Total items failed	0

MOT #7	2023-12-15 11:42
MOT test number	297535886586
Result	✓ Passed
Next expiry date	2024-12-14

MOT #6		2022-07-28 13:07
MOT test i	number	828420381703
Result		✓ Passed
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessiv	re movement (5.3.4 (a)
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessiv	re movement (5.3.4 (a)
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MO1 #5	2022-07-28 08:24
MOT test number	970762061909

Result X Failed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

DANGEROUS Nearside Front Outer Tyre has ply or cords exposed 255/40r19 (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MAJOR Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge and cracking (5.2.3 (e))

MOT #4	2021-06-10 12:48
MOT test number	934367732093
Result	✓ Passed

MOT #3	2020-06-29 09:57
MOT test number	360104336152
Result	Passad

MOT #2	2019-07-08 14:36
MOT test number	576866951115
Result	✓ Passed

MOT #1	2018-03-15 08:31
MOT test number	347187985240
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	14 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report here .		≘?

	More info	>
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		
Current registration	NIZ UK	
Plate since		nn
Correct registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte at Info	

Contact info

More info >


CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2014-11-25
Last registration	2023-12-15
Complete history	See info



Registration #1	2014-11-25	7 mi
Registration #2	2018-03-15	28.411 mi
Registration #3	2019-07-08	39.150 mi
Registration #4	2020-06-29	46.101 mi
Registration #5	2021-06-10	50.707 mi
Registration #6		0.00 44
Registration #7		11.777 es
Registration #8		0.00 44
Registration #9		11.777 no

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

50225	Air conditioning
60295	
0482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Adult	94%
Children	85%
Pedestrian	52%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1831 mm
Height	1590 mm
Length	4385 mm
Wheel base	2603 mm
Kerb weight	1585 kg
Max. allowed weight	2185 kg

Additional information

Fuel tank capacity	64 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

Engine number CFGC709246