



report date: 2024-03-28

General information

Make	CITROEN
Model	C5 VTR PLUS HDI
Colour	Red
Year of manufacture	2009
Top speed	130 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	201 Nm at 4.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	157 g/km
CO2 label	G





Internet history

Entry 2

Date	2023-02-07
Pictures	9
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-06-30
Pictures	21
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-07-30
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	17
Total items failed	10

MOT #17	2023-07-25 12:58
MOT test number	850088507083
Result	✓ Passed
Next expiry date	2024-07-30

MOT #16	2023-07-25 09:35
MOT test number	500983297641
Result	✗ Failed
Fail	Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
Fail	Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
Fail	Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

MOT #15	2022-07-27 15:23
MOT test number	909832119633
Result	✓ Passed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Offside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Rear Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #14**

2022-07-27 13:56

**MOT test number**

711664309959

**Result**

✗ Failed

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge Close to limit. (5.2.3 (e))

**Minor** Offside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Offside Rear Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #13**

2021-07-31 16:29

**MOT test number**

426910566313

**Result**

✓ Passed

**Advice** Anti-roll bar linkage pin or bush worn but not resulting in excessive movement Both rear d bushes (5.3.4 (a) (i))

**Advice** Brake disc worn, but not excessively Both front (1.1.14 (a) (i))

**MOT #12**

2020-10-15 12:01

**MOT test number**

307943208248

**Result**

✓ Passed

**MOT #11**

2020-10-15 08:26

**MOT test number**

561974061678

**Result**

✗ Failed

**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #10** 2019-05-03 15:48**MOT test number** 654578269631**Result** ✓ Passed**Advice** Undertrays and some covers fitted impeding parts of the inspection**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #9** 2018-07-16 16:26**MOT test number** 364209328445**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2016-06-14 11:10**MOT test number** 783737878916**Result** ✓ Passed**MOT #7** 2016-06-14 11:10**MOT test number** 744707023282**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively split (8.2.2)**MOT #6** 2016-05-20 11:06**MOT test number** 841346117384**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)



<b>MOT #5</b>	2015-03-19 15:46
---------------	------------------

<b>MOT test number</b>	869628775059
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2015-03-19 13:20
---------------	------------------

<b>MOT test number</b>	935368775096
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Fail</b>	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
-------------	---

<b>MOT #3</b>	2014-02-18 10:22
---------------	------------------

<b>MOT test number</b>	147829144000
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2013-04-09 13:24
---------------	------------------

<b>MOT test number</b>	569089793017
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2012-03-08 15:57
---------------	------------------

<b>MOT test number</b>	345168262047
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
30 July 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	30 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-03-31
Last registration	2023-07-25
Complete history	<a href="#">See info</a>



Registration #1	2009-03-31	11 mi
Registration #2	2012-03-08	27.105 mi
Registration #3	2013-04-09	35.007 mi
Registration #4	2014-02-18	46.298 mi
Registration #5	2015-03-19	55.999 mi
Registration #6	2015-03-19	55.999 mi
Registration #7	2016-05-20	70.461 mi
Registration #8	2016-06-14	71.639 mi
Registration #9	2016-06-14	71.639 mi
Registration #10	2018-07-16	75.893 mi
Registration #11	2019-05-20	75.893 mi
Registration #12	2019-05-20	75.893 mi
Registration #13	2019-05-20	75.893 mi
Registration #14	2019-05-20	75.893 mi
Registration #15	2019-05-20	75.893 mi
Registration #16	2019-05-20	75.893 mi
Registration #17	2019-05-20	75.893 mi
Registration #18	2019-05-20	75.893 mi
Registration #19	2019-05-20	75.893 mi
Registration #20	2019-05-20	75.893 mi

More info >



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1860 mm
Height	1451 mm
Length	4779 mm
Wheel base	2815 mm
Kerb weight	1521 kg
Max. allowed weight	2155 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	DYVP4020567