



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 E4 D SE V50
Colour	Blue
Year of manufacture	2006
Top speed	130 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-31
Pictures	43
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-20
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	30
Total items failed	5

MOT #19	2023-06-19 11:47
MOT test number	722308900304
Result	✓ Passed
Next expiry date	2024-06-20

MOT #18	2022-06-21 14:08
MOT test number	667581301359
Result	✓ Passed

- Advice** Nearside Front Nail in tyre
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Nail in tyre
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #17** 2022-06-21 12:53**MOT test number** 165262824619**Result** ✗ Failed

- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Nail in tyre
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Front Headlamp light source and lamp not compatible HID kit fitted (4.1.4 (c))
- Advice** Nearside Front Nail in tyre
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #16** 2021-05-25 12:30**MOT test number** 834590316924**Result** ✓ Passed**MOT #15** 2020-05-19 09:56**MOT test number** 738575373129**Result** ✓ Passed**MOT #14** 2019-05-19 17:31**MOT test number** 445244711015**Result** ✓ Passed

**MOT #13** 2018-05-17 11:56**MOT test number** 393118828252**Result** ✓ Passed**Advice** Exhaust box outer skin heavily corroded**MOT #12** 2017-06-17 15:02**MOT test number** 661619096853**Result** ✓ Passed**MOT #11** 2017-06-17 10:13**MOT test number** 901684695141**Result** ✗ Failed**Fail** Offside Front Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #10** 2016-08-10 15:32**MOT test number** 180975842224**Result** ✓ Passed**Advice** EXHAUST REAR BOX CORRODED.**Advice** Coil spring corroded BOTH REAR. (2.4.C.1b)**Advice** EXHAUST HEAT SHIELD INSECURE.

**MOT #9** 2016-07-29 09:12**MOT test number** 696465963554**Result** ✗ Failed**Advice** Coil spring corroded BOTH REAR. (2.4.C.1b)**Advice** EXHAUST HEAT SHIELD INSECURE.**Fail** Registration plate lamp not working BOTH. (1.1.C.1d)**Advice** EXHAUST REAR BOX CORRODED.**MOT #8** 2015-07-14 16:32**MOT test number** 989015395175**Result** ✓ Passed**MOT #7** 2014-07-22 16:55**MOT test number** 829373104230**Result** ✓ Passed**MOT #6** 2013-07-25 13:58**MOT test number** 498696703288**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2012-07-27 16:00**MOT test number** 915119102229**Result** ✓ Passed**Notice** Osf tyre worn on inner edge**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2012-07-21 10:21**MOT test number** 395023002240**Result** ✗ Failed**Fail** Offside Rear Brake pad(s) insecure (3.5.1g)**Notice** Osf tyre worn on inner edge**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-07-25 09:59**MOT test number** 585216601204**Result** ✓ Passed**MOT #2** 2010-07-23 10:03**MOT test number** 421254700256**Result** ✓ Passed**Notice** Nail in offside rear tyre**Notice** N/s front tyre on 3mm, and n/s rear tyre on 2mm.**MOT #1** 2009-08-01 09:24**MOT test number** 534173019276**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
20 June 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	20 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>DA06WXU</b>
Plate since	2024-03-29
Current registration	<b>DA06WXU</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-07-31
Last registration	2023-06-19
Complete history	<a href="#">See info</a>



Registration #1	2006-07-31	12 mi
Registration #2	2009-08-01	26.316 mi
Registration #3	2010-07-23	33.201 mi
Registration #4	2011-07-25	40.661 mi
Registration #5	2012-07-21	48.027 mi
Registration #6	2012-07-27	48.141 mi
Registration #7	2013-07-25	56.266 mi
Registration #8	2014-07-22	66.210 mi
Registration #9	2015-07-14	73.888 mi
Registration #10	2016-07-29	82.739 mi
Registration #11	2016-08-10	82.956 mi
Registration #12	2016-08-10	82.956 mi
Registration #13	2016-08-10	82.956 mi
Registration #14	2016-08-10	82.956 mi
Registration #15	2016-08-10	82.956 mi
Registration #16	2016-08-10	82.956 mi
Registration #17	2016-08-10	82.956 mi
Registration #18	2016-08-10	82.956 mi
Registration #19	2016-08-10	82.956 mi
Registration #20	2016-08-10	82.956 mi
Registration #21	2016-08-10	82.956 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4514 mm
Wheel base	2640 mm
Kerb weight	1489 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	4014833