





### General information

Make	VAUXHALL
Model	VECTRA SRI NAV 16V
Colour	Beige
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	38.7 mpg





# Internet history

Entry	1
Date	

Pictures

2021-09-14

15

Listing price

View report



source: autotrader.co.uk



# MOT history

MOT #16	2022-10-20 14:45
MOT test number	118873842293
Result	✓ Passed
Next expiry date	2023-10-19
Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	)
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (	(b))
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #15	2022-10-13 15:30
MOT test number	653765196598
Result	× Failed
Fail Front Exhaust has a major leak of exhaust gases flexy (6.1.2 (a))	
Fail Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
<b>Fail</b> Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))	
FailFuel cap/sealing device ineffective (6.1.3 (b) (i))	
<b>Fail</b> Nearside Rear Tyre tread depth below requirements of 1.6mm 215/50-17 (5.2.3 (e)	)
Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #14	2021-09-13 14:29
MOT test number	425631896952
Result	✓ Passed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))

MOT #13	2020-12-14 11:26
MOT test number	148514226232
Result	✓ Passed



<b>DS57</b>	Y	E	G
report date:	202	24-0	3-29

MOT test number 95725776889 Result Yaile
Result × Faile
<ul><li>Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))</li><li>Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))</li></ul>
MOT #11 2019-12-07 11:2
<b>MOT test number</b> 45766269070
Result VPasse
<b>MOT #10</b> 2018-12-14 17:0

MOT test number	722659991972
Result	✓ Passed

МОТ #9	2017-12-16 08:51
MOT test number	755430034155
Result	✓ Passed

MOT #8	2016-12-17 10:50
MOT test number	561416227510
Result	✓ Passed

MOT #7	2015-12-21 14:46
MOT test number	814426685163
Result	✓ Passed





MOT #6	2015-12-19 09:27
MOT test number	460933460179
Result	🗙 Failed
Fail         Offside Rear coil spring broken (2.4.C.1a)	
FailNearside Rear coil spring broken (2.4.C.1a)	
Fail         Brake pipe excessively corroded main (3.6.B.2c)	
MOT #5	2014-12-06 11:32
MOT test number	776930644378
Result	✓ Passed
MOT #4	2013-12-07 12:13
MOT test number	459081143494
Result	✓ Passed
MOT #3	2012-12-08 11:05
MOT test number	718533442300
Result	✓ Passed
MOT #2	2011-12-17 11:18
MOT test number	899591151396
Result	✓ Passed
MOT #1	2010-12-18 09:16
MOT test number	284512550358
Result	✓ Passed





### Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET O
Category	APMPE
Туре	
Damage 2	AMPLE
Date	
Category	AMPL
Туре	

#### Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





## Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
AND	
**********	
NUMBER OF CONTRACTOR OF CONTRA	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





### Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-12-31
Last registration	2022-10-20
Complete history	<u>See info</u>



Registration #1	2007-12-31	24 mi
Registration #2	2010-12-18	34.324 mi
Registration #3	2011-12-17	43.343 mi
Registration #4	2012-12-08	51.369 mi
Registration #5	2013-12-07	59.726 mi
Registration #6	2014-12-06	68.692 mi
Registration #7	2015-12-19	77.733 mi
Registration #8	2015-12-21	77.733 mi
Registration #9	2016-12-17	84.877 mi
Registration #10		11.777 est
Registration #11		11.777 est
Registration #12		11.777 est
Registration #13		11.777 est
Registration #14		11.777 esi
Registration #15		11.777 esi
Registration #16		11.177 est
Registration #17		11.777 est
Registration #18		01.202 est





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1346 kg
Max. allowed weight	1885 kg
Additional information	
Additional information Fuel tank capacity	61
	61 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 5