





report date: 2024-03-29

### General information

Make	ТОУОТА
Model	RAV-4 VVTI XTR
Colour	Black
Year of manufacture	2007
Top speed	109 mph
0 - 60 mph	12.0 seconds
Gearbox	4 speed automatic

### Engine & fuel consumption

Power	150 BHP
Max. torque	194 Nm at 4.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	24.4 mpg
Consumption extra urban	38.2 mpg
Consumption combined	31.4 mpg
CO2 emission	212 g/km
CO2 label	K



CarCheck.co.uk page 1/15



report date: 2024-03-29

### Internet history

#### Entry 1

Date 2021-06-05


Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-29

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-07-30
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	39
Total items failed	9

MOT #19	2023-07-31 10:59
MOT test number	921907662491
Result	✓ Passed
Next expiry date	2024-07-30

MOT #18	2022-07-29 14:21
MOT test number	575277398650
Result	✓ Passed

MOT #17	2021-07-26 10:39
MOT test number	991382468129
Result	<b>✓</b> Passed
Advice Covers obscuring some components	

2021-07-23 16:03
557795456140
<b>X</b> Failed

CarCheck.co.uk page 3/15



report date: 2024-03-29

**MOT #15** 2021-01-18 13:37

**MOT test number** 563481092426

**MOT #14** 2021-01-15 14:37

**MOT test number** 901340639043

Result X Failed

Fail Offside Rear Anti-roll bar linkage insecurely attached snapped (5.3.3 (a) (i))

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))

Fail Central Rear Seat belt installation anchorage insecure missing (10.1 (d))

**MOT #13** 2019-07-05 13:17

MOT test number 815196573751

**Result** ✓ Passed

**MOT #12** 2018-06-22 10:44

**MOT test number** 762418755137

**Result** 
✓ Passed

**Advice** Both sides front wishbones bushes deteriorated

Advice Brake pad(s) wearing thin Nearside more so as brake was binding (1.1.13 (a) (ii))

**Advice** Both sides rear drop link buses perished

**Advice** Signs of corrosion in places

Advice Brake disc worn, pitted or scored, but not seriously weakened All (1.1.14 (a) (ii))

**Advice** Rear wiper blade deteriorated

**Advice** Rear coil springs corroded

CarCheck.co.uk page 4/15



report date: 2024-03-29

**MOT #11** 2018-06-22 10:44 **MOT** test number 774395298738 Result **X** Failed **Advice** Rear coil springs corroded Pass with rectification Registration plate lamp inoperative in the case of a single lamp or all lamps Both rear (4.7.1 (b) (ii)) Advice Both sides front wishbones bushes deteriorated Advice Brake disc worn, pitted or scored, but not seriously weakened All (1.1.14 (a) (ii)) Advice Both sides rear drop link buses perished Pass with rectification Nearside Front Position lamp not working (4.2.1 (a)) **Advice** Signs of corrosion in places Pass with rectification Nearside Front Service brake grabbing severely (1.2.1 (c)) **Advice** Rear wiper blade deteriorated **Advice** Brake pad(s) wearing thin Nearside more so as brake was binding (1.1.13 (a) (ii))

MOT #10 2017-07-03 12:01 MOT test number 145667614790

**Result** ✓ Passed

**MOT #9** 2017-06-30 09:29

MOT test number 566080309654

Result × Failed

**Fail** Exhaust has a major leak of exhaust gases middle (7.1.2)

**Advice** Parking brake lever has little reserve travel (3.1.6b)

CarCheck.co.uk page 5/15



report date: 2024-03-29

MOT #8		2016-03-12 09:30
MOT test	number	687230045502
Result		✓ Passed
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)	

MOT #7		2015-02-11 15:42
MOT test	number	427722645010
Result		✓ Passed
MOT #6		2014-04-17 10:02
MOT test	number	125487604139
Result		✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt	
Notice	Offside front tyre slightly perished	

MOT #5		2013-04-03 14:05
MOT test	number	706453893065
Result		✓ Passed
Notice	Air bag on passengers side turned off for child seat no child seat fitted	
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Vehicle's internal headlight adjuster altered to recheck lights	
Notice	Under-trays fitted obscuring some underside components	
Notice	Items removed from driver's view prior to test	

CarCheck.co.uk page 6/15



report date: 2024-03-29

MOT #4		2013-04-02 10:44
MOT test	number	167952993005
Result		<b>×</b> Failed
Notice	Both rear tyres cracking in tread and sidewall areas	
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Vehicle's internal headlight adjuster altered to recheck lights	
Notice	Offside rear tyre has cut in tread area deep enough to reach cords not failure	
<b>Fail</b> N	earside Rear Tyre has ply or cords exposed (4.1.D.1b)	
Notice	Air bag on passengers side turned off for child seat no child seat fitted	
Notice	Under-trays fitted obscuring some underside components	
Notice	Items removed from driver's view prior to test	
Notice	Nail in nearside front tyre	

MOT #3		2012-03-31 10:48
MOT test	number	128731792451
Result		✓ Passed
Notice	Passenger air bag warning lamp on	
Notice	Both rear tyres starting to pereish/crack between tread blocks	

MOT #2	2011-04-07 14:55
MOT test number	986427291019
Result	<b>✓</b> Passed
Notice The front brake discs are showing signs of corrosion and scoring	

CarCheck.co.uk page 7/15



report date: 2024-03-29

MOT #1

MOT test number

233256400494

Result

Notice Front brake discs slightly pitted

233256400494

CarCheck.co.uk page 8/15



report date: 2024-03-29

## Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	30 July 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 9/15



report date: 2024-03-29

#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-29

0	و من مطما ما
Owner	nistory

o met motory	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
HARMAN CO.	
***************************************	
THE PROPERTY OF THE PROPERTY O	
*********	
***************************************	
THE STREET STREET	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	AK (NA)
Plate since	
	More info >

CarCheck.co.uk page 12/15



report date: 2024-03-29

#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-04-28
Last registration	2023-07-31
Complete history	See info



Registration #1	2007-04-28	24 mi
Registration #2	2010-04-16	19.236 mi
Registration #3	2011-04-07	23.437 mi
Registration #4	2012-03-31	28.086 mi
Registration #5	2013-04-02	34.552 mi
Registration #6	2013-04-03	34.558 mi
Registration #7	2014-04-17	40.663 mi
Registration #8	2015-02-11	46.207 mi
Registration #9	2016-03-12	60.760 mi
Registration #10	2017-06-30	73.258 mi
Registration #11	2017-07-03	73.408 mi
Registration #12		71.777 es
Registration #13		71.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		11.777 esi
Registration #20		11.777 es
Registration #21		11.777 es

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-29

## Car features

50225	Air conditioning
50295	
50482	
60501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1815 mm
Height	1720 mm
Length	4395 mm
Wheel base	2560 mm
Kerb weight	1560 kg
Max. allowed weight	2110 kg

## Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 15/15

**Engine number** 

1AZ5678590