



Mercedes-Benz

**GP55LTT**

report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	B-CLASS B200 CDI SE
Colour	Black
Year of manufacture	-
Top speed	121 mph
0 - 60 mph	9.7 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	138 BHP
Max. torque	300 Nm at 3.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg





Internet history

Entry 1

Date	2021-07-27
Pictures	10
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #17</b>	2021-03-26 14:08
<b>MOT test number</b>	613010558579
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-03-25
<b>Advice</b> Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users blue (8.2.2.2 (c))	
<b>Advice</b> Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
<b>Advice</b> Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
<b>Advice</b> Slight play in offside of steering rack but not excessive	
<b>Advice</b> Offside Front Tyre slightly damaged/cracking or perishing but no cords seen (5.2.3 (d) (ii))	

<b>MOT #16</b>	2021-03-16 13:04
<b>MOT test number</b>	715592937499
<b>Result</b>	✗ Failed
<b>Fail</b> Nearside Brake pipe excessively corroded front to rear (1.1.11 (c))	
<b>Advice</b> Slight play in offside of steering rack but not excessive	
<b>Fail</b> Nearside Side repeater not working (4.4.1 (a) (ii))	
<b>Advice</b> Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
<b>Fail</b> Nearside Coil spring fractured or broken (5.3.1 (b) (i))	
<b>Advice</b> Offside Front Tyre slightly damaged/cracking or perishing but no cords seen (5.2.3 (d) (ii))	
<b>Fail</b> Offside Brake pipe excessively corroded front to rear (1.1.11 (c))	
<b>Advice</b> Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users blue (8.2.2.2 (c))	
<b>Fail</b> Offside Steering rack gaiter missing or no longer prevents the ingress of dirt insecure (2.1.3 (g) (ii))	
<b>Advice</b> Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

**MOT #15** 2019-12-31 10:46**MOT test number** 681632403296**Result** ✓ Passed**Advice** Offside Play in steering rack inner joint(s)**Advice** Nearside front inner constant velocity joint gaiter slightly deteriorated**MOT #14** 2019-04-04 15:27**MOT test number** 185857986807**Result** ✓ Passed**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #13** 2018-07-27 14:23**MOT test number** 996731338434**Result** ✓ Passed**Advice** Offside and nearside front tyres wearing heavily on outer edges**Advice** Front brake discs worn**MOT #12** 2017-07-14 15:59**MOT test number** 763240787851**Result** ✓ Passed**MOT #11** 2017-07-11 15:57**MOT test number** 567350278003**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Offside Steering rack gaiter insecure (2.2.D.2d)**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #10** 2016-07-20 11:17**MOT test number** 621733780036**Result** ✓ Passed**MOT #9** 2015-07-17 11:51**MOT test number** 269748095109**Result** ✓ Passed**Notice** Offside and nearside front tyres worn on outer edges**MOT #8** 2014-07-31 18:03**MOT test number** 885792714274**Result** ✓ Passed**MOT #7** 2014-07-31 09:48**MOT test number** 348602614295**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Direction indicator not working (1.4.A.2c)**Fail** Offside Front Steering arm has relative movement at its fixings (2.2.B.1h)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #6** 2013-07-13 15:22**MOT test number** 479554493194**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #5** 2013-07-06 10:37**MOT test number** 617587883153**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Notice** Under-trays fitted obscuring some underside components**Fail** Service brake: efficiency below requirements (3.7.B.7)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #4** 2012-07-24 11:37**MOT test number** 215076302206**Result** ✓ Passed**MOT #3** 2011-11-29 08:54**MOT test number** 675443531394**Result** ✓ Passed**MOT #2** 2010-12-16 08:52**MOT test number** 922400850330**Result** ✓ Passed**MOT #1** 2009-12-17 11:35**MOT test number** 973581659346**Result** ✓ Passed



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	<b>GP55LTT</b>
Plate since	2019-03-29
Current registration	<b>GP55LTT</b>
Plate since	2019-03-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-01-16
Last registration	2021-03-26
Complete history	<a href="#">See info</a>



Registration #1	2006-01-16	20 mi
Registration #2	2009-12-17	22.201 mi
Registration #3	2010-12-16	28.532 mi
Registration #4	2011-11-29	33.048 mi
Registration #5	2012-07-24	36.207 mi
Registration #6	2013-07-06	59.092 mi
Registration #7	2013-07-13	60.196 mi
Registration #8	2014-07-31	65.418 mi
Registration #9	2014-07-31	65.418 mi
Registration #10	2015-07-17	68.904 mi
Registration #11	2016-06-20	70.277 mi
Registration #12	2016-06-20	70.277 mi
Registration #13	2016-06-20	70.277 mi
Registration #14	2016-06-20	70.277 mi
Registration #15	2016-06-20	70.277 mi
Registration #16	2016-06-20	70.277 mi
Registration #17	2016-06-20	70.277 mi
Registration #18	2016-06-20	70.277 mi
Registration #19	2016-06-20	70.277 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1435 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	64094130178237