



Mercedes-Benz



KN64PNF


report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	CLA CLA220 CDI AMG SPORT
Colour	Silver
Year of manufacture	2014
Top speed	143 mph
0 - 100 km/h	8.2 seconds
0 - 60 mph	8.2 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	125 kW / 170 HP / 170 BHP
Max. torque	350 Nm at 1.400 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	111 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-12-10
Pictures	22
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-17
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	25
Total items failed	15

MOT #12	2024-01-17 16:40
MOT test number	959327527566
Result	✓ Passed
Next expiry date	2025-01-17

MOT #11	2024-01-17 11:11
MOT test number	241779564625
Result	✗ Failed

- Fail

Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail

Offside Front Lower Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice

No RPM/smoke detected for emissions test
- Fail

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail

Nearside Headlamp aim too high (4.1.2 (a))
- Fail

Nearside Front Lower Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #10**

2023-01-17 16:28

MOT test number

149989511586

Result

✓ Passed

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** No RPM detected for smoke emissions test**MOT #9**

2023-01-16 10:48

MOT test number

816471353118

Result

✗ Failed

Advice Nearside Front Tyre slightly damaged/cracking or perishing sidewall (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** No RPM detected for smoke emissions test**Fail** Nearside Front Tyre has ply or cords exposed inner edge (5.2.3 (d) (ii))**Fail** Nearside Headlamp aim too high (4.1.2 (a))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Advice** Front Tyre worn close to legal limit/worn on edge x2 (5.2.3 (e))**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure inner edge (5.2.3 (d) (ii))**Fail** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #8** 2022-01-18 14:57**MOT test number** 936265529151**Result** ✓ Passed**MOT #7** 2022-01-18 14:57**MOT test number** 611495308685**Result** ✗ Failed**Pass with rectification** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #6** 2021-03-04 11:36**MOT test number** 380144827438**Result** ✓ Passed**Advice** No emissions peak detected**Advice** Engine noise**Advice** Nearside Front brake hose plastic clip not clipped in to shock correctly**Advice** Rear Tyre worn close to legal limit/worn on edge both rear tyres wearing smooth/worn smooth on inner edges also 3mm approx (225 40 18 92w) (5.2.3 (e))**Advice** Brake disc worn, but not excessively all 4 (1.1.14 (a) (i))**Advice** Undertrays obscuring view also front of undertray is broken/missing

**MOT #5** 2021-03-04 08:54**MOT test number** 453547175337**Result** ✗ Failed**Advice** Rear Tyre worn close to legal limit/worn on edge both rear tyres wearing smooth/worn smooth on inner edges also 3mm approx (225 40 18 92w) (5.2.3 (e))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Engine noise**Advice** Nearside Front brake hose plastic clip not clipped in to shock correctly**Advice** Brake disc worn, but not excessively all 4 (1.1.14 (a) (i))**Advice** Undertrays obscuring view also front of undertray is broken/missing**Advice** No emissions peak detected**Fail** Central Obligatory mirror missing (3.3 (a))**MOT #4** 2020-03-07 10:02**MOT test number** 272320609355**Result** ✓ Passed**MOT #3** 2019-03-28 16:27**MOT test number** 669276485111**Result** ✓ Passed**MOT #2** 2018-04-10 14:21**MOT test number** 677370952527**Result** ✓ Passed**Advice** Front tyres 3mm**MOT #1** 2017-05-24 08:18**MOT test number** 988043831929**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✓
MOT

Expires:
17 January 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	17 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From
Owner	From
Owner	From
Owner	From
Owner	From
Owner	From
Owner	From

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 KN64PNF
Plate since	2019-03-29
Current registration	 KN64PNF
Plate since	2019-03-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-10-29
Last registration	2024-01-17
Complete history	See info



Registration #1	2014-10-29	27 mi
Registration #2	2017-05-24	30.154 mi
Registration #3	2018-04-10	35.001 mi
Registration #4	2019-03-28	73.077 mi
Registration #5	2020-03-07	58.730 mi
Registration #6	2021-03-04	80.372 mi
Registration #7	2021-03-04	80.373 mi
Registration #8	2022-03-07	80.377 mi
Registration #9	2022-03-07	80.377 mi
Registration #10	2022-03-07	80.377 mi
Registration #11	2022-03-07	80.377 mi
Registration #12	2022-03-07	80.377 mi
Registration #13	2022-03-07	80.377 mi
Registration #14	2022-03-07	80.377 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	81%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1777 mm
Height	1432 mm
Length	4630 mm
Wheel base	2699 mm
Kerb weight	1525 kg
Max. allowed weight	2005 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	65193032120397