





General information

Make	ΤΟΥΟΤΑ
Model	URBAN CRUISER VVT-I
Colour	Purple
Year of manufacture	2009
Top speed	109 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.329 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	51.4 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1	
Date	2022-04-16
Pictures	13

Listing price

View report









source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-23
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	17
Total items failed	4

MOT #16	2024-03-15 11:31
MOT test number	428092450105
Result	✓ Passed
Next expiry date	2025-03-23

MOT #15	2023-03-24 16:34
MOT test number	510301215132
Result	✓ Passed

MOT #14	2023-03-23 14:46
MOT test number	298621466994
Result	🗙 Failed
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Nearside Front Headlamp has a product on the lens but not seriously re(b))	educing light output (4.1.4
Fail Nearside Registration plate lamp inoperative in the case of a single lamp of	or all lamps (4.7.1 (b) (ii))
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Headlamp has a product on the lens but not seriously red (b))	lucing light output (4.1.4

MOT #13	2022-04-25 16:11
MOT test number	830677091777
Result	✓ Passed





MOT #12		2021-06-04 08:22
MOT test	number	615320180086
Result		Passed
Advice (b))	Offside Front Headlamp has a product on the lens but not seriously reduci	ing light output (4.1.4
Advice (b))	Nearside Front Headlamp has a product on the lens but not seriously redu	icing light output (4.1.4
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #11		2021-06-04 08:22
MOT test number		577956826465
Result		🗙 Failed
Advice Nearside Front H (b))	leadlamp has a product on the lens but not seriously	reducing light output (4.1.4
Advice Offside Front Ty	re worn close to legal limit/worn on edge (5.2.3 (e))	
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice Nearside Front T	yre worn close to legal limit/worn on edge (5.2.3 (e))
Advice Offside Front He	adlamp has a product on the lens but not seriously r	educing light output (4.1.4

MOT #10		2020-06-17 13:49
MOT test	number	617968172021
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	



EA09HYV	V
report date: 2024-03	-29

MOT #9	2020-06-16 08:36
MOT test number	901032475922
Result	🗙 Failed
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Nearside Front Service brake excessively binding (1.2.1 (f))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #8	2019-04-01 08:34
MOT test number	278355813398
Result	✓ Passed

MOT #7	2018-03-27 08:37
MOT test number	483837216363
Result	✓ Passed

МОТ #6	2017-03-14 09:50
MOT test number	114192222336
Result	✓ Passed

MOT #5	2016-04-08 13:47
MOT test number	250476194035
Result	✓ Passed

MOT #4		2015-06-01 11:38
MOT test	number	305012555103
Result		✓ Passed
Notice	Small cracks in offside rear tyre	
Notice	Small cracks in nearside rear tyre	



🗸 Passed



2014-06-04 13:01
127515254116
✓ Passed
2013-06-04 12:50
957175953148
✓ Passed
2012-05-24 11:54
767165642165

Result



Tax & MOT check

✓ Taxed Tax due: 1 May 2025	✓ MOT Expires: 23 March 2025
Tax status	Valid until 1 May
Days left	366
MOT expiry date	23 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	AMPLI
Damage 2	E E H - S - A
Date	*
Category	AMP.
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-06-12
Last registration	2024-03-15
Complete history	See info



Registration #1	2009-06-12	28 mi
Registration #2	2012-05-24	14.632 mi
Registration #3	2013-06-04	18.539 mi
Registration #4	2014-06-04	23.094 mi
Registration #5	2015-06-01	26.706 mi
Registration #6	2016-04-08	29.031 mi
Registration #7	2017-03-14	39.827 mi
Registration #8	2018-03-27	50.265 mi
Registration #9	2019-04-01	55.152 mi
Registration #10		11.777 est
Registration #11		11.777 est
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi
Registration #18		11.117 mi





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	58%
Children	71%
Pedestrian	53%
Safety systems	86%
Overall rating	62%
Video	see crash video



Dimensions & weight	
Width	1725 mm
Height	1525 mm
Length	3930 mm
Wheel base	2460 mm
Kerb weight	1150 kg
Max. allowed weight	1590 kg
Additional information	
Fuel tank capacity	42
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	1NR0070358