





report date: 2024-03-28

General information

| Make | PEUGEOT |
|---------------------|----------------|
| Model | 307 S |
| Colour | Silver |
| Year of manufacture | - |
| Top speed | 118 mph |
| 0 - 60 mph | 10.7 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 107 BHP |
|-------------------------|---------------------|
| Max. torque | 147 Nm at 4.000 rpm |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 29.7 mpg |
| Consumption extra urban | 48.7 mpg |
| Consumption combined | 39.2 mpg |



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2021-10-28

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-09-10

Pictures 4

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT #17 | 2022-07-14 09:55 |
|------------------|------------------|
| MOT test number | 435279352260 |
| Result | ✓ Passed |
| Next expiry date | 2023-07-13 |

MOT #16

2021-07-02 09:02

MOT test number

254634822954

Result

Advice Exhaust has a minor leak of exhaust gases down pipe gasket slight leak (6.1.2 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))

| MOT #15 | | 2021-01-29 15:24 |
|----------|--|------------------|
| MOT test | number | 929731021451 |
| Result | | ✓ Passed |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Engine oil leak | |
| Minor | Nearside Headlamp lens slightly defective (4.1.1 (b) (i)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e)) | |
| Minor | Offside Headlamp lens slightly defective (4.1.1 (b) (i)) | |

CarCheck.co.uk page 3/12



MOT #14 2021-01-29 12:40

MOT test number 296898808323

Result X Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

Fail Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Engine oil leak

Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))

MOT #13 2019-06-25 15:39

MOT test number 723072641013

Result ✓ Passed

MOT #12 2019-06-25 15:39

MOT test number 832594928648

Result X Failed

Pass with rectification Nearside Rear Position lamp not working (4.2.1 (a) (ii))

Pass with rectification Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the

ingress of dirt (5.3.4 (b) (ii))

Pass with rectification Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the

ingress of dirt (5.3.4 (b) (ii))

MOT #11 2018-06-26 17:02

MOT test number 109894583889

CarCheck.co.uk page 4/12



MOT test number

Result

Advice Front All direction indicators slightly discoloured (4.4.3 (a))

Fail Stop lamp(s) all not working all (4.3.1 (a) (iii))

Advice Nearside Steering rack has slight free play detected at steering wheel (2.3 (a) (ii))

| Advice Nearside Steering rack has slight free play detected at steering wheel (2.3 (a) (i)) | | |
|---|--------|------------------|
| MOT #9 | | 2017-06-24 13:41 |
| MOT test | number | 112476700505 |
| Result | | ✓ Passed |
| | | |
| MOT #8 | | 2016-06-29 15:38 |
| MOT test | number | 582780944955 |
| Result | | ✓ Passed |
| | | |
| MOT #7 | | 2015-07-01 12:01 |
| MOT test | number | 736922985191 |
| Result | | ✓ Passed |
| | | |
| MOT #6 | | 2014-06-21 14:29 |
| MOT test | number | 257242074465 |
| Result | | ✓ Passed |
| | | |
| MOT #5 | | 2013-06-29 09:32 |
| MOT test | number | 897390683133 |
| Result | | ✓ Passed |

| MOT #4 | 2012-06-07 16:24 |
|-----------------|------------------|
| MOT test number | 975669452197 |
| Result | ✓ Passed |

CarCheck.co.uk page 5/12



| MOT #3 | 2011-07-01 11:10 |
|-----------------|------------------|
| MOT test number | 567362581108 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2010-07-01 09:15 |
| MOT test number | 714782680117 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2009-06-18 09:53 |
| MOT test number | 720989069118 |
| Result | √ Passed |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is | |
|---|-------------|
| | |
| | |
| | |
| *************************************** | |
| | |
| | |
| | |
| *************************************** | |
| Diato shanges | More info > |
| Plate changes See in this check if this PEUGEOT had different number plates. | |
| Number of plates | , |
| Current registration | UK UK |
| Plate since | |
| Current registration | UK NE |
| Plate since | |
| | Moro info |

CarCheck.co.uk page 9/12



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| 0.1.116 | |

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 20 |
| First mileage registration | 2006-07-03 |
| Last registration | 2022-07-14 |
| Complete history | See info |



| Registration #1 | 2006-07-03 | 26 mi |
|------------------|------------|-----------|
| Registration #2 | 2009-06-18 | 13.827 mi |
| Registration #3 | 2010-07-01 | 19.145 mi |
| Registration #4 | 2011-07-01 | 22.938 mi |
| Registration #5 | 2012-06-07 | 26.999 mi |
| Registration #6 | 2013-06-29 | 31.240 mi |
| Registration #7 | 2014-06-21 | 35.732 mi |
| Registration #8 | 2015-07-01 | 40.800 mi |
| Registration #9 | 2016-06-29 | 44.943 mi |
| Registration #10 | 2017-06-24 | 50.214 mi |
| Registration #11 | | 9.70 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 9.79 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | 9.79 es |
| Registration #16 | | 11.777 es |
| Registration #17 | | 9.79 es |
| Registration #18 | | 11.777 es |
| Registration #19 | | D.777 es |
| Registration #20 | | 11.777 au |

More info >

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditionin |
|-------|-----------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 60566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1746 mm |
|---------------------|---------|
| Height | 1512 mm |
| Length | 4202 mm |
| Wheel base | 2608 mm |
| Kerb weight | 1275 kg |
| Max. allowed weight | 1700 kg |

Additional information

| Fuel tank capacity | 60 I |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 12/1 |

Number of axles 2

Engine number FX6N2815197