



**BK59UBE**


report date: 2024-03-29

General information

Make	AUDI
Model	A3 TDI S LINE
Colour	White
Year of manufacture	2009
Top speed	133 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	143 g/km
CO2 label	F







Internet history

Entry 1

Date	2021-01-27
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-09-29
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	15
Total items failed	11

MOT #17	2023-09-25 09:46
MOT test number	941121778536
Result	✓ Passed
Next expiry date	2024-09-29
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn rear swinging arm bushes showing signs of wear and perished badly (5.1.2 (b) (i))

MOT #16	2022-09-16 10:50
MOT test number	262713182983
Result	✓ Passed

MOT #15	2022-09-16 10:50
MOT test number	175504606732
Result	✗ Failed
Pass with rectification	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))



<b>MOT #14</b>	2021-09-30 12:54
<b>MOT test number</b>	394713625114
<b>Result</b>	✓ Passed
<b>Minor</b>	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #13</b>	2021-09-30 12:54
<b>MOT test number</b>	537617834336
<b>Result</b>	✗ Failed
<b>Minor</b>	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Pass with rectification</b>	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #12</b>	2020-09-14 14:24
<b>MOT test number</b>	617633212986
<b>Result</b>	✓ Passed

<b>MOT #11</b>	2020-09-08 16:57
<b>MOT test number</b>	266310543792
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
<b>Fail</b>	Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))
<b>Fail</b>	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

<b>MOT #10</b>	2019-10-12 09:58
<b>MOT test number</b>	653350729570
<b>Result</b>	✓ Passed

**MOT #9** 2018-10-13 10:38**MOT test number** 227621270953**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2017-10-26 12:25**MOT test number** 199928369015**Result** ✓ Passed**MOT #7** 2016-10-07 11:29**MOT test number** 236234957102**Result** ✓ Passed**MOT #6** 2016-10-04 15:31**MOT test number** 900650021551**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Service brake: efficiency below requirements (3.7.B.7)**Fail** Nearside Rear Rear position lamp(s) not working (1.1.A.3b)**MOT #5** 2015-10-09 11:02**MOT test number** 325143464383**Result** ✓ Passed**Advice** Nearside Rear tyre cracking**Advice** Offside Rear tyre feathering on inner edge

**MOT #4** 2014-09-01 16:16**MOT test number** 519934244294**Result** ✓ Passed**MOT #3** 2013-09-30 16:26**MOT test number** 737183873229**Result** ✓ Passed**MOT #2** 2013-09-30 15:35**MOT test number** 758373973211**Result** ✗ Failed**Fail** Headlamp aim not tested (1.8.A.1c)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #1** 2012-09-28 10:25**MOT test number** 129802572273**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Notice** Nearside front tyre has deep cut in side wall but not deep enough to reach plys!**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✓  
**MOT**  
  
Expires:  
29 September 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	29 September 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-29
Last registration	2023-09-25
Complete history	<a href="#">See info</a>



Registration #1	2009-09-29	10 mi
Registration #2	2012-09-28	57.828 mi
Registration #3	2013-09-30	77.393 mi
Registration #4	2013-09-30	77.393 mi
Registration #5	2014-09-01	85.613 mi
Registration #6	2015-10-09	100.545 mi
Registration #7	2016-10-04	110.594 mi
Registration #8	2016-10-07	110.728 mi
Registration #9	2017-10-26	129.719 mi
Registration #10	2018-10-13	140.625 mi
Registration #11	2019-09-29	151.531 mi
Registration #12	2020-09-29	162.437 mi
Registration #13	2021-09-29	173.343 mi
Registration #14	2022-09-29	184.249 mi
Registration #15	2023-09-29	195.155 mi
Registration #16	2024-09-29	206.061 mi
Registration #17	2025-09-29	216.967 mi
Registration #18	2026-09-29	227.873 mi
Registration #19	2027-09-29	238.779 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1765 mm
Height	1423 mm
Length	4286 mm
Wheel base	2578 mm
Kerb weight	1385 kg
Max. allowed weight	1945 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	CBA505749