



report date: 2024-03-29

General information

Make	MAZDA
Model	6 D SPORT
Colour	Silver
Year of manufacture	2009
Top speed	135 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 1.800 rpm
Engine capacity	2.184 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-06-16
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-03-10
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	40
Total items failed	17

MOT #202024-04-06 10:14

MOT test number618268031913

Result	Failed
Fail	Service brake excessively binding Nearside + Offside Rear (1.2.1 (f))
Advice	Suspension arm pin or bush worn but not resulting in excessive movement Nearside + Offside Front Rear Bush (5.3.4 (a) (i))
Minor	Front Headlamp lens slightly defective (4.1.1 (b) (i))
Fail	Offside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Brake pipe excessively corroded Nearside + Offside Rear Into Hose (1.1.11 (c))
Minor	Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

**MOT #19**

2024-02-26 09:55

MOT test number

455806238351

Result**✗ Failed**

- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Fail** Nearside Windscreen washer not working (3.5 (a))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Fail** Offside Windscreen washer not working (3.5 (a))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Minor** Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

MOT #18

2023-03-09 13:02

MOT test number

543063854547

Result**✓ Passed**

- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Headlights faded
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Front Lower Suspension arm corroded but not seriously weakened N/S and O/S (5.3.3 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** DPF Light on
- Advice** Towbar Electrics Plug Corroded
- Minor** Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

**MOT #17**

2023-03-03 11:36

MOT test number

465554694785

Result**✗ Failed**

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Towbar Electrics Plug Corroded
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Nearside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Fail** Front Brakes imbalanced across an axle by more than 50% (1.2.1 (b) (ii))
- Advice** Headlights faded
- Minor** Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Advice** DPF Light on
- Advice** Front Lower Suspension arm corroded but not seriously weakened N/S and O/S (5.3.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 215/50/17 (5.2.3 (e))

MOT #16

2022-03-11 13:41

MOT test number

857551367601

Result**✓ Passed**

- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Minor** Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15**

2022-01-31 11:11

MOT test number

490663867472

Result**✗ Failed**

- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Rear Sub-frame corroded and seriously weakened (5.3.3 (b) (i))
- Minor** Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #14

2020-12-01 13:39

MOT test number

397573583602

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing chunk out side wall (5.2.3 (d) (ii))

MOT #13

2020-12-01 13:39

MOT test number

477383247137

Result**✗ Failed**

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing chunk out side wall (5.2.3 (d) (ii))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))



MOT #12	2019-12-04 10:43
---------	------------------

MOT test number	885069581365
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #11	2019-03-15 13:01
---------	------------------

MOT test number	389289495597
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #10	2018-03-20 11:25
---------	------------------

MOT test number	477226381329
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #9	2017-03-24 08:49
--------	------------------

MOT test number	796745045672
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #8	2016-03-07 15:08
--------	------------------

MOT test number	668259506221
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #7	2016-03-07 09:48
--------	------------------

MOT test number	586767296039
-----------------	--------------

Result	✗ Failed
--------	----------

Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
------	---

MOT #6	2015-03-18 16:45
--------	------------------

MOT test number	347127575001
-----------------	--------------

Result	✓ Passed
--------	----------

**MOT #5** 2015-03-17 09:15**MOT test number** 109846075080**Result** ✗ Failed**Fail** Nearside Front Mechanical brake component has restricted free movement (3.5.1k)**Fail** Offside Front Mechanical brake component has restricted free movement (3.5.1k)**MOT #4** 2014-03-29 10:03**MOT test number** 109288784423**Result** ✓ Passed**MOT #3** 2014-03-28 13:04**MOT test number** 615047084078**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2013-03-25 11:03**MOT test number** 315064783081**Result** ✓ Passed**MOT #1** 2012-03-17 10:06**MOT test number** 385267472000**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✗
MOT

Expired:
10 March 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	10 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-




Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-04-03
Last registration	2024-04-06
Complete history	See info



Registration #1	2009-04-03	12 mi
Registration #2	2012-03-17	36.773 mi
Registration #3	2013-03-25	49.027 mi
Registration #4	2014-03-28	58.388 mi
Registration #5	2014-03-29	58.388 mi
Registration #6	2015-03-17	65.660 mi
Registration #7	2015-03-18	65.660 mi
Registration #8	2016-03-07	74.661 mi
Registration #9	2016-03-07	74.661 mi
Registration #10	2017-03-24	82.193 mi
Registration #11	2018-03-20	89.191 mi
Registration #12	2019-03-20	95.277 mi
Registration #13	2019-03-20	95.277 mi
Registration #14	2019-03-20	95.277 mi
Registration #15	2019-03-20	95.277 mi
Registration #16	2019-03-20	95.277 mi
Registration #17	2019-03-20	95.277 mi
Registration #18	2019-03-20	95.277 mi
Registration #19	2019-03-20	95.277 mi
Registration #20	2019-03-20	95.277 mi
Registration #21	2019-03-20	95.277 mi
Registration #22	2019-03-20	95.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	77%
Children	81%
Pedestrian	49%
Safety systems	71%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Kerb weight	1560 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R2 10203473