



AV530HB


report date: 2024-03-28

General information

Make	AUDI
Model	TT V6 QUATTRO
Colour	Silver
Year of manufacture	2003
Top speed	155 mph
0 - 60 mph	6.4 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	247 BHP
Max. torque	320 Nm at 2.800 rpm
Engine capacity	3.189 cc
Cylinders	6
Fuel type	Petrol
Consumption city	13.6 mpg
Consumption extra urban	7.6 mpg
Consumption combined	9.8 mpg
CO2 emission	238 g/km
CO2 label	L





MOT history

MOT expiry date	2024-11-23
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	27
Total items failed	8

MOT #22	2023-11-24 09:56
MOT test number	799998031638
Result	✓ Passed
Next expiry date	2024-11-23

MOT #21	2022-10-27 15:25
MOT test number	879253920085
Result	✓ Passed

MOT #20	2022-10-05 13:13
MOT test number	969116074092
Result	✗ Failed
Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	

MOT #19	2021-10-06 17:24
MOT test number	270755225511
Result	✓ Passed

**MOT #18**

2020-09-29 12:01

MOT test number

232179224974

Result

✓ Passed

Advice Nearside Rear Brake pipe corroded, covered in grease or other material Combination pipe (1.1.11 (c))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

Advice Oil leak, but not excessive Engine area (8.4.1 (a) (i))

Advice Nearside Rear Nail in tyre

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

MOT #17

2019-06-27 07:22

MOT test number

996307979962

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #16

2018-06-28 09:49

MOT test number

547601421763

Result

✓ Passed

MOT #15

2018-06-27 16:08

MOT test number

670262107050

Result

✗ Failed

Fail Nearside Rear Service brake excessively binding (1.2.1 (f))

**MOT #14** 2017-06-26 19:30**MOT test number** 798486711083**Result** ✓ Passed**MOT #13** 2016-07-01 10:16**MOT test number** 863213211698**Result** ✓ Passed**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Under-trays fitted.**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**MOT #12** 2015-06-29 15:10**MOT test number** 529170085133**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #11** 2014-06-26 18:29**MOT test number** 247167474176**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**MOT #10**

2014-06-24 18:40

MOT test number

535085774170

Result**✗ Failed****Advice**

Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Fail

Nearside Front position lamp(s) not working (1.1.A.3b)

Fail

Offside Front Headlamp cleaning device obviously defective (1.7.2)

Fail

Nearside Front Headlamp cleaning device obviously defective (1.7.2)

MOT #9

2013-06-27 15:13

MOT test number

467108273174

Result**✓ Passed****Notice**

Engine covers fitted obscuring some components in the engine bay

Advice

Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Notice

Under-trays fitted obscuring some underside components

MOT #8

2013-06-26 12:15

MOT test number

456927073119

Result**✗ Failed****Notice**

Offside front Tyre wearing slightly on inner edge.

Notice

Engine covers fitted obscuring some components in the engine bay

Fail

Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Notice

Under-trays fitted obscuring some underside components

Advice

Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**MOT #7** 2012-06-28 12:30**MOT test number** 806040482192**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #6** 2011-06-03 12:20**MOT test number** 625824751169**Result** ✓ Passed**MOT #5** 2010-06-15 12:15**MOT test number** 231936360496**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #4** 2010-06-15 12:15**MOT test number** 972966060137**Result** ✓ Passed**MOT #3** 2009-06-17 13:07**MOT test number** 204488469113**Result** ✓ Passed**MOT #2** 2008-07-01 15:43**MOT test number** 102413188141**Result** ✓ Passed**Notice** Slight damage to n/s/f tyre wall



MOT #1	2007-01-26 09:47
MOT test number	193136127494
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
23 November 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	23 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-




Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2003-09-29
Last registration	2023-11-24
Complete history	See info



Registration #1	2003-09-29	21 mi
Registration #2	2007-01-26	31.758 mi
Registration #3	2008-07-01	39.681 mi
Registration #4	2009-06-17	43.858 mi
Registration #5	2010-06-15	49.056 mi
Registration #6	2011-06-03	56.023 mi
Registration #7	2012-06-28	57.984 mi
Registration #8	2013-06-26	59.572 mi
Registration #9	2013-06-27	59.572 mi
Registration #10	2014-06-24	62.135 mi
Registration #11	2014-06-26	62.135 mi
Registration #12	2015-06-29	65.277 mi
Registration #13	2015-06-29	65.277 mi
Registration #14	2015-06-29	65.277 mi
Registration #15	2015-06-29	65.277 mi
Registration #16	2015-06-29	65.277 mi
Registration #17	2015-06-29	65.277 mi
Registration #18	2015-06-29	65.277 mi
Registration #19	2015-06-29	65.277 mi
Registration #20	2015-06-29	65.277 mi
Registration #21	2015-06-29	65.277 mi
Registration #22	2015-06-29	65.277 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1764 mm
Height	1345 mm
Length	4041 mm
Wheel base	2429 mm
Kerb weight	1590 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	BHE 003709