



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	B-CLASS B180 CDI BLUEEFFICIENCY SPORT
Colour	White
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	11.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	117 g/km
CO2 label	C





Internet history

Entry 2

Date	2022-10-30
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-13
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-26
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	24
Total items failed	6

MOT #13 2023-10-26 10:15**MOT test number** 107444500214**Result** ✓ Passed**Next expiry date** 2024-10-26**Advice** Revers light no working**Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**MOT #12** 2022-10-24 09:13**MOT test number** 812728680127**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2022-10-24 09:13**MOT test number** 648387403481**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2021-10-27 15:33**MOT test number** 657507584977**Result** ✓ Passed**MOT #9** 2020-11-26 13:02**MOT test number** 867764729217**Result** ✓ Passed

- Advice** Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #8 2020-11-26 10:31**MOT test number** 421402648933**Result** ✗ Failed

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #7 2019-11-28 09:30**MOT test number** 189996506195**Result** ✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #6** 2018-11-15 13:53**MOT test number** 368587277096**Result** ✓ Passed**MOT #5** 2018-11-15 11:13**MOT test number** 739341382918**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #4** 2017-11-16 14:10**MOT test number** 575221520175**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #3** 2017-11-16 10:59**MOT test number** 536530453415**Result** ✗ Failed**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #2** 2016-10-20 13:48**MOT test number** 226957724305**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Under trays and engine covers fitted



MOT #1	2016-10-20 11:32
MOT test number	565748453382
Result	✗ Failed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Under trays and engine covers fitted



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
26 October 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	26 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 VK63NCU
Plate since	2019-03-29
Current registration	 VK63NCU
Plate since	2019-03-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-11-19
Last registration	2023-10-26
Complete history	See info



Registration #1	2013-11-19	19 mi
Registration #2	2016-10-20	15.560 mi
Registration #3	2016-10-20	15.562 mi
Registration #4	2017-11-16	30.207 mi
Registration #5	2017-11-16	30.208 mi
Registration #6	2018-11-15	44.813 mi
Registration #7	2018-11-15	44.813 mi
Registration #8	2019-11-28	58.257 mi
Registration #9	2019-11-28	58.257 mi
Registration #10	2019-11-28	58.257 mi
Registration #11	2019-11-28	58.257 mi
Registration #12	2019-11-28	58.257 mi
Registration #13	2019-11-28	58.257 mi
Registration #14	2019-11-28	58.257 mi
Registration #15	2019-11-28	58.257 mi
Registration #16	2019-11-28	58.257 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	81%
Pedestrian	56%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2010 mm
Height	1542 mm
Length	4359 mm
Wheel base	2699 mm
Kerb weight	1475 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	K9KF452D022666