





report date: 2024-03-28

General information

| Make | PEUGEOT |
|---------------------|-------------------|
| Model | 508 HDI SW ACTIVE |
| Colour | White |
| Year of manufacture | 2014 |
| Top speed | 130 mph |
| 0 - 60 mph | 10.1 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 140 BHP |
|-------------------------|---------------------|
| Max. torque | 320 Nm at 2.000 rpm |
| Engine capacity | 1.997 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 44.1 mpg |
| Consumption extra urban | 72.4 mpg |
| Consumption combined | 58.9 mpg |
| CO2 emission | 125 g/km |
| CO2 label | D |



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2021-02-03

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

| MOT expiry date | 2024-07-11 |
|--------------------|------------|
| MOT pass rate | 88 % |
| MOT passed | 7 |
| Failed MOT tests | 1 |
| Total advice items | 7 |
| Total items failed | 1 |

| MOT #8 | 2023-07-10 08:16 |
|--------------------------------------------------------------------|------------------|
| MOT test number | 244569026260 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-11 |
| Minor Offside Front Obligatory mirror slightly loose (3.3 (b) (i)) | |

| MOT #7 | | 2022-07-12 15:05 |
|----------|---------------------------------------------------------------------------|------------------|
| MOT test | number | 329367518109 |
| Result | | ✓ Passed |
| Advice | Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice | Nearside Front Tyre slightly damaged Slight kerb damaged (5.2.3 (d) (ii)) | |
| Advice | Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |

| MOT #6 | 2021-05-24 15:07 |
|-----------------|------------------|
| MOT test number | 399076277071 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



report date: 2024-03-28

| MOT #5 | 2021-05-07 11:30 |
|----------------------------------------------------------------------------|------------------|
| MOT test number | 234642491346 |
| Result | × Failed |
| Advice Engine cover fitted not allowing full inspection of some components | |
| Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) | |
| Advice Under trays fitted not allowing full inspection of some components | |

| MOT #4 | 2020-01-22 10:11 |
|---------------------------------------------------------|------------------|
| MOT test number | 626361026903 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2019-01-23 10:19 |
| MOT test number | 596244285500 |
| Result | ✓ Passed |
| Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| MOT #2 | 2018-01-31 09:20 |
|-----------------|------------------|
| MOT test number | 105125722988 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2017-02-01 10:19 |
| MOT test number | 638124345105 |
| Result | ✓ Passed |

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 August |
|------------------|----------------------|
| Days left | 94 |
| MOT expiry date | 11 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|-----------------------------------------|------------|
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

| \sim | | h:a | + |
|--------|------|-----|--------------|
| -C)V | vner | mis | \mathbf{I} |

| For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations. | | GEOT |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|------|
| | | |
| seeses seese | | |
| *************************************** | | |
| *************************************** | | |
| | | |
| | | |
| | | |
| *************************************** | | |
| | More info | > |
| Plate changes | | |
| See in this check if this PEUGEOT had different number plates. | | |
| Number of plates | | |
| Current registration | UK NE | |
| Plate since | | |
| Current registration | UK UK | |
| Plate since | | |
| | More info | > |

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 10 |
| First mileage registration | 2014-02-10 |
| Last registration | 2023-07-10 |
| Complete history | See info |



| Registration #1 | 2014-02-10 | 13 mi |
|---------------------------------|------------|-----------|
| Registration #2 | 2017-02-01 | 21.375 mi |
| Registration #3 | 2018-01-31 | 27.066 mi |
| Registration #4 | 2019-01-23 | 32.279 mi |
| Registration #5 | 2020-01-22 | 36.530 mi |
| | | |
| Registration #6 | | |
| Registration #6 Registration #7 | | 11.777 es |
| | | 11.77 m |
| Registration #7 | | 1.77 m |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 90% |
| Children | 87% |
| Pedestrian | 41% |
| Safety systems | 97% |
| Overall rating | 80% |
| Video | see crash video |



Dimensions & weight

| Width | 1853 mm |
|---------------------|---------|
| Height | 1476 mm |
| Length | 4813 mm |
| Wheel base | 2817 mm |
| Kerb weight | 1500 kg |
| Max. allowed weight | 2140 kg |

Additional information

| Fuel tank capacity | 72 I | |
|-----------------------------------|------------------|------|
| Fuel delivery | Direct Injection | |
| Number of doors | 5 | |
| Number of seats CarCheck.co.uk | 5 page 1: | 1/11 |

Number of axles 2

Engine number DYZA4059448