



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I10 GO
Colour	Blue
Year of manufacture	2016
Top speed	96 mph
0 - 60 mph	14.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	65 BHP
Max. torque	95 Nm at 3.500 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	108 g/km
CO2 label	B





Internet history

Entry 2


Date	2021-06-30
Pictures	23
Listing price	<a href="#">View report</a>



source: yesauto.com

Entry 1

Date	2021-05-21
Pictures	24
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-05-01
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	16
Total items failed	7

MOT #8	2023-05-02 15:47
MOT test number	441646772803
Result	✓ Passed
Next expiry date	2024-05-01
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2023-05-02 05:51
MOT test number	657405450059
Result	✗ Failed
Fail	Nearside Rear Service brake excessively fluctuating (1.2.1 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Rear Service brake excessively fluctuating (1.2.1 (e))

MOT #6	2022-04-27 10:42
MOT test number	745526608586
Result	✓ Passed
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #5** 2021-04-26 09:12**MOT test number** 353630326159**Result** ✓ Passed**MOT #4** 2020-06-22 11:29**MOT test number** 526688572647**Result** ✓ Passed**MOT #3** 2020-06-19 10:43**MOT test number** 285757871734**Result** ✗ Failed**Fail** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Fail** Rear Brake pad(s) less than 1.5 mm thick inner pads (1.1.13 (a) (ii))**MOT #2** 2019-06-01 10:37**MOT test number** 947903260334**Result** ✓ Passed**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge shoulder (5.2.3 (e))**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge shoulder (5.2.3 (e))



MOT #1	2019-05-28 13:49
MOT test number	798466493105
Result	✗ Failed
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge shoulder (5.2.3 (e))
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge shoulder (5.2.3 (e))
Fail	Offside Front Headlamp insecure (4.1.1 (c))
Advice	Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Nearside Front Headlamp insecure (4.1.1 (c))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
1 May 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	1 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-05-31
Last registration	2023-05-02
Complete history	<a href="#">See info</a>



Registration #1	2016-05-31	7 mi
Registration #2	2019-05-28	20.190 mi
Registration #3	2019-06-01	20.191 mi
Registration #4	2020-06-19	26.319 mi
Registration #5	2020-06-22	26.348 mi
Registration #6	2021-04-26	30.017 mi
Registration #7	2023-05-02	35.277 mi
Registration #8	2023-05-02	35.277 mi
Registration #9	2023-05-02	35.277 mi
Registration #10	2023-05-02	35.277 mi
Registration #11	2023-05-02	35.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	79%
Children	80%
Pedestrian	71%
Safety systems	56%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1660 mm
Height	1500 mm
Length	3665 mm
Wheel base	2385 mm
Kerb weight	933 kg
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G3LAFM003200