





### General information

Make	NISSAN
Model	PIXO N-TEC
Colour	Grey
Year of manufacture	2009
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	В







# Internet history

Entry 1

Date

2021-11-04

Pictures

8

Listing price

View report



source: autotrader.co.uk



# MOT history

MOT expiry date	2024-12-26
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	36
Total items failed	10

MOT #18	2023-12-09 09:30
MOT test number	344660002692
Result	✓ Passed
Next expiry date 2024-12-26	
Advice Nearside Front Tyre worn close to legal limit/worn on edge recommend change (5.2.3 (e))	

MOT #17	2022-12-20 11:55
MOT test number	153190006779
Result	✓ Passed
Minor Nearside Front Inner Drive shaft joint constant velocity boot severely de	teriorated (6.1.7 (g) (i))
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #16	2022-12-20 11:55	
MOT test number	380728860527	
Result	× Failed	
Pass with rectification	Offside Front Bumper likely to become detached (6.1.4 (a) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))		





MOT #15	2021-12-17 15:35	
MOT test number	549707277956	
Result	Passed	
MOT #14	2020-12-21 16:06	
MOT test number	827075649183	
Result	✓ Passed	
Advice Driver's view Items removed from driver's view prior to test (3.1 (a) (ii)	)	
<b>Minor</b> Driver's view to the sides outside the swept area of the windscreen wipers restricted by an obstruction (3.1 (a) (i))		
<b>Minor</b> Driver's view to the front outside the swept area of the windscreen wipe obstruction (3.1 (a) (i))	ers restricted by an	

MOT #13		2019-12-27 15:17
MOT test	number	695795168442
Result		✓ Passed
Advice	NAIL IN NSR TYRE	
Advice	Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))	

MOT #12	2019-12-27 14:24
MOT test number	918232157303
Result	🗙 Failed
Advice NAIL IN NSR TYRE	
<b>Fail</b> Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))	

MOT #11	2018-12-19 16:43
MOT test number	259692097832
Result	✓ Passed





МОТ #10	2018-12-19 13:15
MOT test number	394091506199
Result	🗙 Failed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	) (ii))
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail Nearside Rear Service brake excessively binding (1.2.1 (f))	

MOT #9		2017-12-20 17:34
MOT test	number	767508154382
Result		✓ Passed
Advice	Nearside front tyre has cuts on outer sidewall but cords not exposed	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside front and nearside rear doors damaged	
Advice	Front brake discs worn	
Advice	Offside front tyre has cuts on outer wall but cords not exposed	
Advice	Road wheel slightly damaged Both front (4.2.A.1a)	



MOT #8		2017-12-20 17:34
MOT test	number	825338955442
Result		🗙 Failed
Advice	Nearside front and nearside rear doors damaged	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Front brake discs worn	
Advice	Offside front tyre has cuts on outer wall but cords not exposed	
<b>Pass with rectification</b> Offside Rear Tyre(s) incorrect because tyres with different aspect ratios are fitted on the same axle. (4.1.A.1a)		
Advice	Road wheel slightly damaged Both front (4.2.A.1a)	
Advice	Nearside front tyre has cuts on outer sidewall but cords not exposed	

MOT #7		2016-12-15 13:35
MOT test r	number	630421488026
Result		✓ Passed
Advice	Cut on offside front tyre outer sidewall	
Advice	Front brake discs and pads wearing thin	
Advice	Cut on nearside rear tyre outer sidewall	

MOT #6	2015-12-04 11:53
MOT test number	474861599317
Result	✓ Passed

LD59KTK

report date: 2024-03-28





MOT #5		2015-12-03 09:33
MOT tes	t number	660442549934
Result		🗙 Failed
Fail	Nearside Rear Tyre has a tear, caused by separation or partial failure of its stru	cture (4.1.D.1b)
Fail	Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)	
Advice	Nearside Front nail in outside edge of tyre	

MOT #4	2014-11-27 12:23
MOT test number	797151234359
Result	✓ Passed
<b>Notice</b> Two rear tyres. walls starting too crack	

MOT #3		2013-12-03 16:04
MOT test	number	798097833323
Result		✓ Passed
Notice	Both rear tyres outer side walls slight cuts and perished slightly	
Notice	Both front tyres worn on inner and outer edges	

MOT #2		2012-12-07 15:57
MOT test	number	449372142415
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	





MOT #1	2012-12-07 10:06
MOT test number	638562742395
Result	🗙 Failed
Fail Nearside Front Headlamp aim too low (1.8)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail Offside Front Headlamp aim too low (1.8)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

✓ Taxed Tax due: 1 December 2024	✓ MOT Expires: 26 December 2024
Tax status	Valid until 1 December
Days left	217
MOT expiry date	26 December 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





#### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	e et al
Date	*
Category	AMP
Туре	

#### Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





### Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	
************	
********	
*******	
************	
********	
	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-09-30
Last registration	2023-12-09
Complete history	See info



Registration #1	2009-09-30	20 mi
Registration #2	2012-12-07	12.450 mi
Registration #3	2012-12-07	12.450 mi
Registration #4	2013-12-03	14.230 mi
Registration #5	2014-11-27	17.202 mi
Registration #6	2015-12-03	18.978 mi
Registration #7	2015-12-04	19.878 mi
Registration #8	2016-12-15	20.825 mi
Registration #9	2017-12-20	25.345 mi
Registration #10	2017-12-20	25.345 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 est
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		10.207 est
Registration #19		10.207 mi
Registration #20		11.117 mi





### Car features

S0225	Air conditioning
\$0295	
50482	
50501	
50566	
60567	
50569	

# Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

### Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	107462