



P06IXEK

report date: 2024-03-29

General information

Make	MAZDA
Model	3 D TS2
Colour	Black
Year of manufacture	2011
Top speed	115 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	64.2 mpg
CO2 emission	117 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-19
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-06
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	39
Total items failed	3

MOT #14 2023-06-07 10:10

MOT test number 746718453942

Result ✓ Passed

Next expiry date 2024-06-06

Advice Rear Integral body structure is corroded but structural rigidity is not significantly reduced o/s and n/s (6.1.1 (c) (i))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

MOT #13 2023-06-07 10:10

MOT test number 422832765957

Result ✗ Failed

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Rear Integral body structure is corroded but structural rigidity is not significantly reduced o/s and n/s (6.1.1 (c) (i))

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #12**

2022-06-06 09:29

MOT test number

403193161600

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge very close to minimum limit (5.2.3 (e))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Brake pad(s) wearing thin all (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin all (1.1.13 (a) (ii))

MOT #11

2022-05-26 10:11

MOT test number

691071086200

Result

✗ Failed

- Advice** Rear Brake pad(s) wearing thin all (1.1.13 (a) (ii))
- DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin all (1.1.13 (a) (ii))
- DANGEROUS** Offside Front Lower Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge very close to minimum limit (5.2.3 (e))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #10

2021-05-29 13:11

MOT test number

230768504360

Result

✓ Passed

- Advice** Front Suspension arm ball joint has slight play offside & nearside (5.3.4 (a) (i))

**MOT #9** 2020-09-23 15:30**MOT test number** 130737152575**Result** ✓ Passed

- Advice** Vehicle underneath corroded in places
- Advice** Front and Rear suspension components are corroding
- Advice** Exhaust system corroded in places

MOT #8 2020-09-23 08:07**MOT test number** 667984568524**Result** ✗ Failed

MAJOR Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

- Advice** Vehicle underneath corroded in places
- Advice** Front and Rear suspension components are corroding
- Advice** Exhaust system corroded in places

MOT #7 2019-09-19 17:09**MOT test number** 849030719043**Result** ✓ Passed

- Advice** Vehicle corroded underneath in places
- Advice** Both rear trailing arm bushes slightly splitting
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6 2018-09-22 09:15**MOT test number** 916943499503**Result** ✓ Passed

- Advice** Vehicle underneath corroded in places
- Advice** Offside Front Tyre wearing on the edges

**MOT #5** 2017-09-23 10:49**MOT test number** 931635901544**Result** ✓ Passed**Advice** Vehicle underneath corroded in places**MOT #4** 2017-09-23 07:37**MOT test number** 511023870106**Result** ✗ Failed**Advice** Vehicle underneath corroded in places**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure outer sidewall (4.1.D.1b)**MOT #3** 2016-09-23 08:16**MOT test number** 501208985431**Result** ✓ Passed**MOT #2** 2015-09-24 09:05**MOT test number** 927057797173**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2014-09-23 09:23**MOT test number** 117526564247**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
6 June 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	6 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	PO61XEK
Plate since	2024-03-29
Current registration	PO61XEK
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-09-23
Last registration	2023-06-07
Complete history	See info



Registration #1	2011-09-23	9 mi
Registration #2	2014-09-23	27.764 mi
Registration #3	2015-09-24	33.482 mi
Registration #4	2016-09-23	38.113 mi
Registration #5	2017-09-23	42.821 mi
Registration #6	2017-09-23	42.821 mi
Registration #7	2018-09-22	47.932 mi
Registration #8	2019-09-19	51.940 mi
Registration #9	2020-09-23	55.948 mi
Registration #10	2021-09-23	59.956 mi
Registration #11	2022-09-23	63.964 mi
Registration #12	2023-06-07	67.972 mi
Registration #13	2023-06-07	67.972 mi
Registration #14	2023-06-07	67.972 mi
Registration #15	2023-06-07	67.972 mi
Registration #16	2023-06-07	67.972 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	84%
Pedestrian	51%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2002 mm
Height	1470 mm
Length	4480 mm
Wheel base	2640 mm
Kerb weight	1323 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	Y6 336477