




report date: 2024-03-29

General information

Make	VOLVO
Model	V70 SE (170BHP)
Colour	Grey
Year of manufacture	2005
Top speed	130 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	225 Nm at 4.500 rpm
Engine capacity	2.435 cc
Cylinders	5
Fuel type	Petrol
Consumption city	20.3 mpg
Consumption extra urban	37.2 mpg
Consumption combined	28.5 mpg
CO2 emission	234 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-10-08
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-16
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	57
Total items failed	9

MOT #20 2023-10-17 15:58

MOT test number 889622648940

Result ✓ Passed

Next expiry date 2024-10-16

- Advice** Rear Coil spring corroded o/s & n/s (5.3.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner face's (1.1.14 (a) (ii))
- Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Headlamp lens slightly defective o/s & n/s (4.1.1 (b) (i))
- Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Offside headlight pattern poor
- Advice** Front Coil spring corroded o/s & n/s (5.3.1 (b) (i))
- Advice** Rear Brake hose has slight corrosion to ferrule o/s & n/s (1.1.12 (f) (i))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))



MOT #19

2023-10-09 11:01

MOT test number

423370970382

Result		✗ Failed
Advice	Offside headlight pattern poor	
Advice	Rear Brake hose has slight corrosion to ferrule o/s & n/s (1.1.12 (f) (i))	
Minor	Headlamp lens slightly defective o/s & n/s (4.1.1 (b) (i))	
Advice	Rear Coil spring corroded o/s & n/s (5.3.1 (b) (i))	
Advice	Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice	Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened inner face's (1.1.14 (a) (ii))	
Fail	Rear Anti-roll bar pin or bush excessively worn o/s & n/s mounting bushes (5.3.4 (a) (i))	
Minor	Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	
Advice	Front Coil spring corroded o/s & n/s (5.3.1 (b) (i))	

**MOT #18**

2022-10-06 11:35

MOT test number

485860436891

Result

✓ Passed

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened o/s & n/s [inner face's] (1.1.14 (a) (ii))

Advice

Rear Brake hose has slight corrosion to ferrule o/s & n/s (1.1.12 (f) (i))

Minor

Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice

Front Coil spring corroded o/s & n/s (5.3.1 (b) (i))

Advice

Parking brake lever travel

Advice

Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement mounting [border line] (5.3.4 (a) (i))

Advice

Rear Coil spring corroded o/s & n/s (5.3.1 (b) (i))

Minor

Offside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice

Offside headlight pattern poor

Advice

Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement mounting [border line] (5.3.4 (a) (i))

MOT #17

2021-10-11 18:08

MOT test number

715852884794

Result

✓ Passed

Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #16**

2021-08-17 09:08

MOT test number

993646402324

Result**✗ Failed**

- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge EDGE BALD (5.2.3 (e))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge EDGE BALD (5.2.3 (e))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Offside Rear Outer Tyre worn close to legal limit/worn on edge EDGE BALD TYRE UNDER INFLATED (5.2.3 (e))

MOT #15

2020-08-17 08:08

MOT test number

266534470025

Result**✓ Passed**

- Advice** Offside Rear Outer Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin both (1.1.13 (a) (ii))
- Advice** Front Coil spring corroded both (5.3.1 (b) (i))
- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))

**MOT #14** 2020-08-12 13:05**MOT test number** 652011120424**Result** ✗ Failed

- Fail** Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Rear Outer Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin both (1.1.13 (a) (ii))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Fail** Brake lever has insufficient reserve travel (1.1.2 (a))
- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Coil spring corroded both (5.3.1 (b) (i))

MOT #13 2019-07-24 13:08**MOT test number** 865377932844**Result** ✓ Passed**MOT #12** 2019-07-24 10:44**MOT test number** 421273400128**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge inside tread (5.2.3 (e))
- Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #11** 2018-07-24 11:08**MOT test number** 469464725889**Result** ✓ Passed**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #10** 2017-07-21 10:38**MOT test number** 965967680240**Result** ✓ Passed**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**MOT #9** 2016-07-21 14:31**MOT test number** 784467462219**Result** ✓ Passed**MOT #8** 2015-07-22 14:20**MOT test number** 401567745193**Result** ✓ Passed**MOT #7** 2014-08-08 11:53**MOT test number** 955820924202**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #6** 2013-08-19 11:37**MOT test number** 146381233256**Result** ✓ Passed**MOT #5** 2012-10-10 15:37**MOT test number** 917914782244**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-10-12 11:36**MOT test number** 135225081263**Result** ✓ Passed**MOT #3** 2010-10-13 10:17**MOT test number** 372846280475**Result** ✓ Passed**MOT #2** 2009-10-14 15:48**MOT test number** 734727889252**Result** ✓ Passed**MOT #1** 2008-10-08 13:33**MOT test number** 754892688298**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
16 October 2024

Tax status	Valid until 1 May
Days left	368
MOT expiry date	16 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-10-11
Last registration	2023-10-17
Complete history	See info



Registration #1	2005-10-11	18 mi
Registration #2	2008-10-08	41.130 mi
Registration #3	2009-10-14	53.568 mi
Registration #4	2010-10-13	62.326 mi
Registration #5	2011-10-12	71.333 mi
Registration #6	2012-10-10	78.536 mi
Registration #7	2013-08-19	87.718 mi
Registration #8	2014-08-08	101.570 mi
Registration #9	2015-07-22	111.149 mi
Registration #10	2016-07-21	119.883 mi
Registration #11	2017-07-21	124.750 mi
Registration #12	2018-06-20	131.557 mi
Registration #13	2019-06-19	138.364 mi
Registration #14	2020-06-18	145.171 mi
Registration #15	2021-06-17	151.978 mi
Registration #16	2022-06-16	158.785 mi
Registration #17	2023-06-15	165.592 mi
Registration #18	2024-06-14	172.399 mi
Registration #19	2025-06-13	179.206 mi
Registration #20	2026-06-12	186.013 mi
Registration #21	2027-06-11	192.820 mi
Registration #22	2028-06-10	199.627 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1804 mm
Height	1465 mm
Length	4710 mm
Wheel base	2755 mm
Kerb weight	1525 kg
Max. allowed weight	2130 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	3779181