



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO JTD DYNAMIC (90BHP)
Colour	Grey
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	11.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	200 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	72.4 mpg
Consumption combined	61.4 mpg



**MOT history**

MOT #19	2020-10-06 16:04
MOT test number	702613346552
Result	✓ Passed
Next expiry date	2021-10-05

MOT #18	2020-10-06 09:39
MOT test number	558391690945
Result	✗ Failed

- Fail** Offside Driver's door cannot be opened from inside the vehicle (6.2.3 (a))
- Fail** Offside Front Inner Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))
- Fail** Offside Rear Outer Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Fail** Nearside Rear Outer Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #17	2019-09-05 11:58
MOT test number	508082124149
Result	✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge rear tyre tread on outer edge just legal (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge tyre tread on outer edge just legal (5.2.3 (e))

MOT #16	2019-09-05 11:58
MOT test number	321858487107
Result	✗ Failed

Pass with rectification

Nearside Rear Position lamp not working (4.2.1 (a) (ii))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge rear tyre tread on outer edge just legal
(5.2.3 (e))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge tyre tread on outer edge just legal
(5.2.3 (e))

**MOT #15** 2018-09-07 14:22**MOT test number** 979228513572**Result** ✓ Passed**MOT #14** 2018-09-07 11:32**MOT test number** 652911094140**Result** ✗ Failed**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Driver's view of the road through the swept area of the windscreen materially affected by an obstruction (3.1 (a) (ii))**MOT #13** 2017-06-12 11:02**MOT test number** 615959694910**Result** ✓ Passed**Advice** Eml light on**Advice** Stone chip in windscreen**MOT #12** 2016-05-18 09:12**MOT test number** 236368725152**Result** ✓ Passed**Advice** Rear Shock absorber has a light misting of oil Both shock absorbers (2.7.3)**Advice** Eml light on?**Advice** Oil leak**Advice** Centre Rear Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)**Advice** Exhaust rear box corroded also heatshield insecure**Advice** Nearside Rear Nail**Advice** Front brake disc worn, pitted or scored, but not seriously weakened Both discs (3.5.1i)

**MOT #11**

2016-05-16 11:38

MOT test number

129498706237

Result**✗ Failed**

- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Exhaust system rear back box heat shield insecure
- Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)
- Advice** Nail nearside rear tyre
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)
- Advice** Centre Rear Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)
- Advice** Engine cover fitted obscuring some components
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Oil leak
- Advice** Exhaust system rear back box deteriorated
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Parking brake lever ratchet mechanism is slightly worn (3.1.5)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)



MOT #102015-05-18 17:49

MOT test number955178435111

Result		✓ Passed
Advice	Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)	
Notice	Engine management light on	
Notice	Offside handbrake cable in poor condition	
Advice	Front Sub-frame corroded but not seriously weakened (2.4.G.1)	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)	
Notice	Slight side movement in parking brake lever	
Advice	Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)	
Notice	Front brake discs pitted	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

**MOT #9** 2015-05-18 17:24**MOT test number** 378268135166**Result** ✗ Failed**Advice** Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Slight side movement in parking brake lever**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Notice** Offside handbrake cable in poor condition**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)**Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)**Notice** Engine management light on**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Notice** Front brake discs pitted**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #8** 2014-04-02 16:47**MOT test number** 998012794090**Result** ✓ Passed**Advice** Front Vehicle structure has slight corrosion (6.1.B.2)



MOT #7 2014-04-02 16:47

MOT test number 128202094422

Result ✗ Failed

Pass with rectification Nearside Lower Rear position lamp(s) not working (1.1.A.3b)

Pass with rectification Offside Lower Rear position lamp(s) not working (1.1.A.3b)

Advice Front Vehicle structure has slight corrosion (6.1.B.2)

Pass with rectification Nearside Upper Rear position lamp(s) not working (1.1.A.3b)

Pass with rectification Offside Upper Rear position lamp(s) not working (1.1.A.3b)

MOT #6 2013-01-07 16:53

MOT test number 928417003082

Result ✓ Passed

Advice Offside Front Macpherson strut worn but not seriously weakened (2.4.G.1)

Notice NSR upper sidelight inop

Notice Handbrake slow to pull up on OS, efficiency OK

MOT #5 2013-01-07 10:29

MOT test number 679407603015

Result ✗ Failed

Notice NSR upper sidelight inop

Fail Offside Front coil spring fractured (2.4.C.1a)

Notice Handbrake slow to pull up on OS, efficiency OK

**MOT #4** 2012-01-05 14:31**MOT test number** 758125602046**Result** ✓ Passed**Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**MOT #3** 2012-01-04 12:57**MOT test number** 417614902086**Result** ✗ Failed**Fail** Front Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2010-11-09 12:41**MOT test number** 851923010353**Result** ✓ Passed**Notice** Front suspension /spring platform areas coroding,radiator bottom hose damp ??**MOT #1** 2009-11-28 09:34**MOT test number** 872102639396**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-11-29
Last registration	2020-10-06
Complete history	See info



Registration #1	2006-11-29	19 mi
Registration #2	2009-11-28	38.920 mi
Registration #3	2010-11-09	51.744 mi
Registration #4	2012-01-04	64.083 mi
Registration #5	2012-01-05	64.083 mi
Registration #6	2013-01-07	72.133 mi
Registration #7	2013-01-07	72.133 mi
Registration #8	2014-04-02	76.764 mi
Registration #9	2015-05-18	80.730 mi
Registration #10	2015-05-18	80.730 mi
Registration #11	2016-05-18	85.730 mi
Registration #12	2017-05-18	90.730 mi
Registration #13	2018-05-18	95.730 mi
Registration #14	2019-05-18	100.730 mi
Registration #15	2020-05-18	105.730 mi
Registration #16	2021-05-18	110.730 mi
Registration #17	2022-05-18	115.730 mi
Registration #18	2023-05-18	120.730 mi
Registration #19	2024-03-29	125.730 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1130 kg
Max. allowed weight	2690 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	1286806