





### General information

Make	ΤΟΥΟΤΑ	
Model	HILUX ACTIVE 4WD D-4D S/C	
Colour	Silver	
Year of manufacture	2017	
Top speed	106 mph	
0 - 60 mph	12.8 seconds	
Gearbox	6 speed Manual	

### Engine & fuel consumption

Power	150 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.393 сс
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	44.1 mpg
Consumption combined	39.8 mpg
CO2 emission	187 g/km
CO2 label	J







### Internet history


Entry 2

Date Pictures 2021-10-22

6

Listing price

View report









source: cargurus.co.uk

#### Entry 1

Date

**Pictures** 

Listing price

2021-10-21 6

View report

source: autotrader.co.uk









# MOT history

MOT expiry date	2024-05-24
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	14
Total items failed	0

MOT #6	2023-05-25 16:02
MOT test number	101506647017
Result	🗸 Passed
Next expiry date	2024-05-24
<ul> <li>Advice Parking brake efficiency only just met. It would appear that the braking system adjustment or repair. Park brake lever also has a lot of travel, but doesn't hit the stop (1.4.2)</li> <li>Advice Nearside front bumper damaged but not likely to cause injury</li> <li>Minor Offside Direction indicator flashing more than 120 times a minute (4.4.4 (a))</li> <li>Minor Nearside Direction indicator flashing more than 120 times a minute (4.4.4 (a))</li> </ul>	•



F	D17LWG
	report date: 2024-03-28

MOT #5	2023-05-19 13:59
MOT test number	532838175653
Result	🗙 Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Minor</b> Offside Direction indicator flashing more than 120 times a minute (4.4.4 (a))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))	
Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords Si	dewall (5.2.3 (d) (i))
<b>Advice</b> Parking brake efficiency only just met. It would appear that the braking system adjustment or repair. Park brake lever also has a lot of travel, but doesn't hit the stop (1.4)	
Advice Nearside front bumper damaged but not likely to cause injury	
<b>Minor</b> Nearside Direction indicator flashing more than 120 times a minute (4.4.4 (a))	
<b>DANGEROUS</b> Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
<b>MAJOR</b> Rear fog lamp not working (4.5.1 (a) (ii))	

MOT #4	2022-04-07 15:04
MOT test number	522406907328
Result	✓ Passed
MOT #3	2021-06-28 13:55
MOT test number	301514413769
Result	✓ Passed
MOT #2	2021-06-21 15:06

MOT test	number	276433323319
Result		🗙 Failed
MAJOR	Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))	





MOT #1	2020-07-07 14:52
MOT test number	889080424584
Result	✓ Passed



Tax & MOT check

√ Taxed	√ MOT
<b>Tax due:</b> 1 April 2025	Expires: 24 May 2024
Tax status	Valid until 1 April
Days left	337
MOT expiry date	24 May 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	J
First licence fee (12 months)	£ 1.040,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.565,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	AMPLI
Damage 2	E E H - S - A
Date	*
Category	AMP.
Туре	

#### Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
**********	
********	
NUMBER OF TAXABLE PARTY	
***********	
********	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-08-09
Last registration	2023-05-25
Complete history	See info



Registration #1	2017-08-09	20 mi
Registration #2	2020-07-07	70.303 mi
Registration #3	2021-06-21	92.503 mi
Registration #4	2021-06-28	92.508 mi
Registration #5		11.777 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 esi

More info >





### Car features

S0225	Air conditionin
\$0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	93%
Children	82%
Pedestrian	83%
Safety systems	63%
Overall rating	83%
Video	see crash video



Additional information	
Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2
Engine number	2GDC124491