



LJ59FXP

report date: 2024-03-29

General information

Make	FORD
Model	S-MAX GHIA TDCI
Colour	Grey
Year of manufacture	2009
Top speed	120 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-04-10
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	40
Total items failed	13

MOT #15	2023-04-11 15:32
---------	------------------

MOT test number	581726176902
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-04-10
------------------	------------

Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Offside Front Obligatory mirror slightly loose (3.3 (b) (i))
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Horn sound low
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #14**

2022-04-01 13:51

MOT test number

223686622685

Result

✓ Passed

- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #13**

2022-04-01 11:23

MOT test number

703379133860

Result**✗ Failed**

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #12

2021-01-04 16:56

MOT test number

616974818547

Result**✓ Passed****MOT #11**

2019-07-18 11:45

MOT test number

290894388542

Result**✓ Passed**

**MOT #10**

2019-07-18 10:04

MOT test number

434151807483

Result**✗ Failed**

- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Tyre has ply or cords exposed 225/50/17 (5.2.3 (d) (ii))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Front Windscreen washer not working (3.5 (a))

MOT #9

2018-08-07 08:58

MOT test number

161531942730

Result**✓ Passed**

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #8

2018-08-06 10:18

MOT test number

285547587557

Result**✗ Failed**

- Fail** Horn not working (7.7 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #7

2017-08-08 10:55

MOT test number

934142608470

Result**✓ Passed**

- Advice** FAS too low to detect, passed visual test.

**MOT #6** 2016-08-10 13:19**MOT test number** 586791732734**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2016-08-10 10:17**MOT test number** 607638106636**Result** ✗ Failed**Fail** Front Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2014-11-07 15:29**MOT test number** 537881514305**Result** ✓ Passed**MOT #3** 2014-11-07 09:49**MOT test number** 567211914325**Result** ✗ Failed**Fail** Nearside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Offside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #2** 2013-11-12 14:52**MOT test number** 449016913447**Result** ✓ Passed**MOT #1** 2012-11-30 11:53**MOT test number** 376525332336**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕
Untaxed

Tax expired:
7 April 2023

✕
MOT

Expired:
10 April 2024

Tax status	Expired at 7 April 2023
Days left	389 days too late
MOT expiry date	10 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-12-22
Last registration	2023-04-11
Complete history	See info



Registration #1	2009-12-22	24 mi
Registration #2	2012-11-30	42.092 mi
Registration #3	2013-11-12	56.734 mi
Registration #4	2014-11-07	73.893 mi
Registration #5	2014-11-07	73.896 mi
Registration #6	2016-08-10	101.732 mi
Registration #7	2016-08-10	101.732 mi
Registration #8	2017-08-08	118.236 mi
Registration #9	2018-08-06	135.474 mi
Registration #10	2019-08-06	152.712 mi
Registration #11	2020-08-06	170.000 mi
Registration #12	2021-08-06	187.288 mi
Registration #13	2022-08-06	204.576 mi
Registration #14	2023-04-11	221.864 mi
Registration #15	2023-04-11	221.864 mi
Registration #16	2023-04-11	221.864 mi
Registration #17	2023-04-11	221.864 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1933 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	9K79192