



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	COUPE ATLANTIC
Colour	Blue
Year of manufacture	2006
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	186 Nm at 4.500 rpm
Engine capacity	1.975 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.3 mpg
CO2 emission	193 g/km
CO2 label	J






Internet history

Entry 1

Date	2022-01-29
Pictures	19
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-20
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	41
Total items failed	10

MOT #21	2023-12-21 14:05
MOT test number	473222639338
Result	✓ Passed
Next expiry date	2024-12-20
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #20	2023-12-11 10:59
MOT test number	651684809926
Result	✗ Failed
Fail	Nearside Rear Anti-roll bar linkage pin or bush likely to become detached (5.3.4 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Front Service brake excessively fluctuating Brake discs warped (1.2.1 (e))

**MOT #19**

2022-12-05 16:45

MOT test number

190259071370

Result

✓ Passed

- Minor** Steering lock not functioning (7.3 (a))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #18

2022-12-01 10:42

MOT test number

710860118655

Result

✗ Failed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Rear Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Steering lock not functioning (7.3 (a))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords outside wall (5.2.3 (d) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17

2021-12-03 16:37

MOT test number

266650537152

Result

✓ Passed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Exhaust has a minor leak of exhaust gases Rear (6.1.2 (a))

**MOT #16** 2020-10-19 09:04**MOT test number** 916950384773**Result** ✓ Passed

- Advice** Rear Exhaust silencer slightly loose (8.1.1 (b) (i))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #15 2019-10-05 11:00**MOT test number** 492275814185**Result** ✓ Passed

- Advice** Front Registration plate insecure but not likely to fall off (0.1 (a))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #14 2019-10-04 10:57**MOT test number** 911299523270**Result** ✗ Failed

- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Advice** Front Registration plate insecure but not likely to fall off (0.1 (a))

MOT #13 2018-10-12 13:23**MOT test number** 558518881863**Result** ✓ Passed**MOT #12** 2017-10-20 14:28**MOT test number** 226254307098**Result** ✓ Passed

**MOT #11** 2016-10-19 13:53**MOT test number** 552725432348**Result** ✓ Passed**Advice** Rear crossmember corroded but seriously weekend.**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #10** 2016-10-12 09:37**MOT test number** 744532150049**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside front brake binding (3.7.B.1)**Advice** Rear crossmember corroded but seriously weekend.**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened badly corroded (3.5.1i)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside rear brake binding (3.7.B.1)**MOT #9** 2015-09-10 11:00**MOT test number** 385476656468**Result** ✓ Passed**Advice** Both rear brake discs corroded and pitted

**MOT #8** 2014-10-01 08:59**MOT test number** 648364974207**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in nearside rear tyre**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2013-09-28 08:26**MOT test number** 446301373210**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #6** 2012-10-02 12:48**MOT test number** 667596872266**Result** ✓ Passed**Notice** Nail in nearside rear tyre**MOT #5** 2011-09-30 11:56**MOT test number** 945033671226**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2010-10-01 09:46**MOT test number** 620174470290**Result** ✓ Passed**Notice** Discs slightly corroded



MOT #3	2010-05-13 09:07
MOT test number	443253930117
Result	✓ Passed

MOT #2	2009-04-21 09:41
MOT test number	113211219162
Result	✓ Passed
<div><div>Advice</div> Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)</div>	

MOT #1	2009-04-21 09:41
MOT test number	153451119134
Result	✗ Failed
<div><div>Pass with rectification</div> Front Windscreen washer provides insufficient washer liquid (8.2.3)</div> <div><div>Pass with rectification</div> Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)</div> <div><div>Advice</div> Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
20 December 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	20 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	SD06WFK
Plate since	2024-03-29
Current registration	SD06WFK
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-05-18
Last registration	2023-12-21
Complete history	See info



Registration #1	2006-05-18	9 mi
Registration #2	2009-04-21	28.373 mi
Registration #3	2010-05-13	38.075 mi
Registration #4	2010-10-01	40.988 mi
Registration #5	2011-09-30	47.374 mi
Registration #6	2012-10-02	53.137 mi
Registration #7	2013-09-28	58.025 mi
Registration #8	2014-10-01	63.338 mi
Registration #9	2015-09-10	67.483 mi
Registration #10	2016-10-12	68.191 mi
Registration #11	2016-10-19	68.193 mi
Registration #12	2017-05-22	68.200 mi
Registration #13	2018-05-22	68.200 mi
Registration #14	2019-05-22	68.200 mi
Registration #15	2020-05-22	68.200 mi
Registration #16	2021-05-22	68.200 mi
Registration #17	2022-05-22	68.200 mi
Registration #18	2023-05-22	68.200 mi
Registration #19	2023-05-22	68.200 mi
Registration #20	2023-05-22	68.200 mi
Registration #21	2023-05-22	68.200 mi
Registration #22	2023-05-22	68.200 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1382 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4GC6670361