





report date: 2024-03-29

### General information

Make	FORD
Model	FUSION FUSION 2
Colour	Red
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed automatic

### Engine & fuel consumption

Power	99 BHP
Max. torque	145 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.2 mpg
Consumption extra urban	46.3 mpg
Consumption combined	36.7 mpg



CarCheck.co.uk page 1/13



report date: 2024-03-29

### Internet history

#### Entry 1


Date 2021-06-10

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

## MOT history

MOT #22	2021-11-05 10:07
MOT test number	498106254100
Result	✓ Passed
Next expiry date	2022-11-04
Advice Both rear tyres starting to wear uneven	
Advice Off side front head light starting to mist over	

MOT #21		2021-11-05 10:07
MOT test number		819483073056
Result		<b>×</b> Failed
Pass with rectification	Front Horn not working (7.7 (a))	
Advice Off side front h	nead light starting to mist over	
Advice Both rear tyres	s starting to wear uneven	

MOT #20	2020-10-26 13:50
MOT test number	401156602801
Result	✓ Passed

MOT #19		2019-09-12 14:58
MOT test	number	263582942285
Result		✓ Passed
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)	)
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Minor	Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

**MOT #18** 2018-05-30 11:05

**MOT test number** 222101741459

**Result** ✓ Passed

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #17** 2018-05-30 11:05

**MOT test number** 590311748699

Result X Failed

**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Pass with rectification** Brake fluid contaminated (1.8 (a))

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #16** 2017-05-11 10:26

**MOT test number** 228268276702

Result Passed

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

**MOT #15** 2017-05-11 10:26

MOT test number 164797384377

**Result** X Failed

**Pass with rectification** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)

**Pass with rectification** Offside Front Tyre has ply or cords exposed (4.1.D.1b)

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #14	2016-05-16 09:57
MOT test number	553128415020
Result	✓ Passed
Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)	

MOT #13		2015-05-01 11:49
MOT test number		377821125136
Result		<b>✓</b> Passed
MOT #12		2014-05-28 11:50
MOT test number		997368144162
Result		✓ Passed
MOT #11		2014-05-28 11:50
MOT test number		289548544142
Result		× Failed
Pass with rectification	Nearside Stop lamp not working (1.2.1b)	

MOT #10	2013-05-24 12:22
MOT test number	817034343186
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/13



Result

WG04FWX

report date: 2024-03-29

✓ Passed

MOT #	9	2013-05-22 15:42
MOT te	st number	549172043140
Result		<b>★</b> Failed
Fail	Offside Front Valve stem seriously damaged (4.1.D.1e)	
Fail	Nearside Rear Valve stem seriously damaged (4.1.D.1e)	
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail	Offside Rear Valve stem seriously damaged (4.1.D.1e)	
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)	

MOT #8	2012-05-29 13:54
MOT test number	226040752127
Result	<b>✓</b> Passed
MOT #7	2012-05-29 10:03
MOT test number	288040552440

F	Result		<b>x</b> Failed
	Fail	Nearside Headlamp aim too low (1.8)	
	Fail	Offside Front Shock absorber has negligible damping effect (2.7.5)	
	Fail	Offside Headlamp aim too low (1.8)	
	Fail	Nearside Front Shock absorber has negligible damping effect (2.7.5)	

MOT #6	2011-06-06 16:25
MOT test number	216397551122
Result	✓ Passed
MOT #5	2010-06-30 09:47
MOT test number	120581780116

CarCheck.co.uk page 6/13



report date: 2024-03-29

MOT #4 2010-06-28 10:57

**MOT test number** 510649970199

Result X Failed

**Fail** Offside Obligatory mirror insecure (8.1.1)

Fail Offside Anti-roll bar has excessive play in a ball joint (2.4.G.2)

MOT #3 2009-08-21 10:52

**MOT test number** 673803739293

**Result** ✓ Passed

**Advice** Offside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)

MOT #2 2008-08-29 13:12

MOT test number 580572648287

**Result** ✓ Passed

**MOT #1** 2007-08-31 14:15

**MOT test number** 720943847273

**Result** ✓ Passed

CarCheck.co.uk page 7/13



report date: 2024-03-29

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

$\hat{}$	
()Whor	hictory
OWILL	11151 OT V
Owner	,

For how long did the current and previous owner(s) have this FORD? How many owners check it in the premium report and see all owner registrations. Download the full report		e?
***************************************		
***************************************		
***************************************		
	More info >	
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		
Current registration	UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 10/13



report date: 2024-03-29

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-05-15
Last registration	2021-11-05
Complete history	See info



Registration #1	2004-05-15	29 mi
Registration #2	2007-08-31	20.011 mi
Registration #3	2008-08-29	24.225 mi
Registration #4	2009-08-21	28.213 mi
Registration #5	2010-06-28	30.267 mi
Registration #6	2010-06-30	30.267 mi
Registration #7	2011-06-06	35.476 mi
Registration #8	2012-05-29	37.204 mi
Registration #9	2012-05-29	37.212 mi
Registration #10	2013-05-22	43.192 mi
Registration #11	2013-05-24	43.192 mi
Registration #12	2014-05-28	47.316 mi
Registration #13		11.177 es
Registration #14		11.117 es
Registration #15		11.177 es
Registration #16		11.117 es
Registration #17		11.177 mi
Registration #18		11.117 es
Registration #19		
Registration #20		0.074
Registration #20 Registration #21		11.777 es
-		11.777 es 11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

### Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1952 mm
Height	1534 mm
Length	4020 mm
Wheel base	2485 mm
Kerb weight	1110 kg

# Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number CarCheck.co.uk	4A46535 page 13/13