





report date: 2024-03-29

General information

Make	BMW
Model	316 316I TRGLX
Colour	White
Year of manufacture	1994
Top speed	109 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	98 BHP
Max. torque	141 Nm at 4.250 rpm
Engine capacity	1.596 сс
Cylinders	4
Fuel type	Petrol



CarCheck.co.uk page 1/13



report date: 2024-03-29


Internet history

Entry 1

Date 2021-10-28

Pictures 18

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2023-09-02
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	31
Total items failed	2

MOT #20		2022-09-01 15:36
MOT test	number	742040787423
Result		✓ Passed
Next expi	ry date	2023-09-02
Advice	Rear fuel pipe has been catching on the ground	
Advice	Vehicles suspension has been modified	
Advice	All jacking points and floor of vehicle corroded	
Advice	Exhaust rear box corroded	
Advice	Unable to fullty assess welding rerpairs due to heavy covering of under seal	

MOI #19	2022-00-24 13.10
MOT test number	147086679471
Result	× Failed

MAJOR Offside Front Integral body structure corroded to the extent that the rigidity of the assembly is

MAJOR Rear fog lamp not working (4.5.1 (a) (ii))

significantly reduced floor and sill (6.1.1 (c) (i))

Advice Rear fuel pipe has been catching on the ground

MAJOR Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction (3.1 (a) (ii))

Advice All jacking points and floor of vehicle corroded

Advice Exhaust rear box corroded

CarCheck.co.uk page 3/13



MOT #14

L904DRU

report date: 2024-03-29

2017-08-25 12:22

MOT #18	2021-09-03 16:17
MOT test number	708306423144
Result	✓ Passed
MOT #17	2020-08-27 07:52
MOT test number	658203990938
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #16	2019-08-27 14:38
MOT test number	286888070984
Result	✓ Passed
Advice Rear exhaust box deteriorated	

MOT #15	2018-08-13 09:46
MOT test number	861989191819
Result	✓ Passed
Advice Rear exhaust box deteriorated	

MOT test number	844785428446
Result	✓ Passed
MOT #13	2016-08-23 09:39
MOT test number	546267160975
Result	✓ Passed
Advice Nearside rear tyre starting to crfack	
Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)	

CarCheck.co.uk page 4/13



report date: 2024-03-29

✓ Passed

MOT test number

Result

Pass with rectification

Nearside Headlamp aim too low (1.8)

Advice

Nearside rear tyre starting to crfack

Advice

Rear Exhaust has a minor leak of exhaust gases (7.1.2)

 MOT #11
 2015-08-21 08:26

 MOT test number
 799266734300

 Result
 ✓ Passed

MOT #10 2014-09-01 15:32 MOT test number 549884044242 Result ✓ Passed

MOT #9 2013-03-25 13:02

MOT test number 145634883015

Result \(\sqrt{Passed} \)

Advice Nearside Front coil spring corroded (2.4.C.1b)

Advice Offside Rear coil spring corroded (2.4.C.1b)

Advice Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)

Advice Offside Front coil spring corroded (2.4.C.1b)

Result

 MOT #8
 2012-03-26 17:24

 MOT test number
 256246482069

CarCheck.co.uk page 5/13



Advice

L904DRU

report date: 2024-03-29

MOT #7

MOT test number

166016582027

Result

Fail Offside Rear rear parking brake recording little or no effort (3.7.B.6a)

Offside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #6

MOT test number

436667281009

Result

Notice Handbrake travel

Notice Power steering fluid leak

MOT #5

MOT test number

243722580063

Result

Notice Handbrake travel

Advice Offside Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #4

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

 MOT #3
 2008-03-26 09:08

 MOT test number
 270986588005

 Result
 ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

MOT test number

Result

Advice

Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2006-03-23 08:52
MOT test number	564162086059
Result	√ Passed

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



L904DRU report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did Check it in the premium report and see all owner registrations. Download the full report in the premium report and see all owner registrations.		ve?

THE STATE OF THE S		

	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		9
Current registration	OK SIE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	1994-03-23
Last registration	2022-09-01
Complete history	See info



Registration #1	1994-03-23	7 mi
Registration #2	2006-03-23	47.038 mi
Registration #3	2007-03-19	48.146 mi
Registration #4	2008-03-26	49.397 mi
Registration #5	2009-03-19	50.011 mi
Registration #6	2010-03-23	50.740 mi
Registration #7	2011-03-28	51.678 mi
Registration #8	2012-03-26	53.244 mi
Registration #9	2012-03-26	53.244 mi
Registration #10	2013-03-25	53.741 mi
Registration #11	2014-09-01	54.145 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 au
Registration #21		11.777 es
Registration #22		71.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
0482	
0501	
0566	
60567	
60569	

Additional information

Engine number	00397853
---------------	----------

CarCheck.co.uk page 13/13