



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D DRIVE R-DESIGN
Colour	White
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history


Entry 1

Date	2021-05-22
Pictures	9
Listing price	View report




NO ADMIN FEES
WE HAVE NO HIDDEN FEES





PRICE PROMISE
WE WEEKLY PRICE CHECK
ALL OF OUR VEHICLES TO
ENSURE THEY ARE PRICED
CORRECTLY





HPI CHECKED
ALL OUR CARS CHECKED
BY EXPERIAN





HOLD THIS CAR?
SECURE THIS CAR TODAY
WITH A £200 HOLDING
DEPOSIT



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-30
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	30
Total items failed	3

MOT #172023-06-26 15:49

MOT test number952862593429

Result✓ Passed

Next expiry date2024-06-30

- Advice** Manufacture fitted undertrays obscuring view of some underbody components
- Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Both, rear bush (5.3.4 (a) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material both (1.1.11 (c))
- Advice** Underbody corrosion
- Advice** Front Coil spring corroded Both (5.3.1 (b) (i))
- Advice** Front Lower Suspension arm corroded but not seriously weakened Both (5.3.3 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both, inner face (1.1.14 (a) (ii))
- Advice** Power steering pipe/hose slightly corroded (2.1.5 (g) (i))

MOT #162022-07-01 13:10

MOT test number777296302522

Result✓ Passed

- Advice** Rear underside corroded.

**MOT #15** 2022-06-24 11:53**MOT test number** 380457706185**Result** ✗ Failed

MAJOR Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Outer boot missing clip. (6.1.7 (g) (ii))

DANGEROUS Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge Inner edge. (5.2.3 (e))

Advice Rear underside corroded.

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Inner edge. (5.2.3 (e))

MOT #14 2021-06-04 14:33**MOT test number** 328670945099**Result** ✓ Passed**MOT #13** 2021-05-27 12:29**MOT test number** 436344126883**Result** ✗ Failed

MAJOR Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

DANGEROUS Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MAJOR Nearside Front Position lamp not working (4.2.1 (a) (ii))

DANGEROUS Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #12 2020-07-01 11:26**MOT test number** 557548640880**Result** ✓ Passed

Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Offside Windscreen wiper blade defective (3.4 (b) (i))

**MOT #11** 2020-07-01 11:26**MOT test number** 439502433191**Result** ✗ Failed**Pass with rectification** Offside Front Direction indicator incorrect colour (4.4.3 (a))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**MOT #10** 2019-07-08 16:15**MOT test number** 492168053235**Result** ✓ Passed**MOT #9** 2019-07-08 11:19**MOT test number** 608181414111**Result** ✗ Failed**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #8** 2018-07-19 14:42**MOT test number** 364739966467**Result** ✓ Passed**MOT #7** 2017-07-18 13:12**MOT test number** 750245136865**Result** ✓ Passed

**MOT #6** 2016-07-21 15:23**MOT test number** 998417317315**Result** ✓ Passed**Advice** Nearside and offside tyres lumpy**MOT #5** 2016-07-21 10:42**MOT test number** 536515388097**Result** ✗ Failed**Advice** Nearside and offside tyres lumpy**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear (2.4.G.2)**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear (2.4.G.2)**MOT #4** 2015-07-29 13:39**MOT test number** 221572973165**Result** ✓ Passed**MOT #3** 2014-07-30 14:04**MOT test number** 189051414221**Result** ✓ Passed**MOT #2** 2013-08-28 10:51**MOT test number** 377150843426**Result** ✓ Passed**MOT #1** 2012-09-18 17:10**MOT test number** 358122562460**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
30 June 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	30 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-11-13
Last registration	2023-06-26
Complete history	See info



Registration #1	2009-11-13	9 mi
Registration #2	2012-09-18	36.323 mi
Registration #3	2013-08-28	43.217 mi
Registration #4	2014-07-30	48.652 mi
Registration #5	2015-07-29	55.513 mi
Registration #6	2016-07-21	64.826 mi
Registration #7	2016-07-21	64.826 mi
Registration #8	2017-07-18	74.187 mi
Registration #9	2018-07-19	83.226 mi
Registration #10	2019-07-08	90.912 mi
Registration #11	2020-06-26	95.513 mi
Registration #12	2021-06-26	100.114 mi
Registration #13	2022-06-26	104.715 mi
Registration #14	2023-06-26	109.316 mi
Registration #15	2024-06-26	113.917 mi
Registration #16	2025-06-26	118.518 mi
Registration #17	2026-06-26	123.119 mi
Registration #18	2027-06-26	127.720 mi
Registration #19	2028-06-26	132.321 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1381 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	704037