





report date: 2024-03-28

## General information

Make	AUDI
Model	Q3 TDI QUATTRO S LINE BLACK EDITI
Colour	Green
Year of manufacture	2018
Top speed	126 mph
0 - 100 km/h	9.3 seconds
0 - 60 mph	9.3 seconds
Gearbox	7 speed automatic

# Engine & fuel consumption

Power	110 kW / 150 HP / 148 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	140 g/km
CO2 label	E



CarCheck.co.uk page 1/11



## Internet history

### Entry 5

Date 2023-10-07

Pictures 36

Listing price <u>View report</u>









### source: cargurus.co.uk

### Entry 4

Date	2023-07-27
Pictures	0
Listing price	View report

### source: cargurus.co.uk

### Entry 3

Date 2021-10-31

Pictures 11

Listing price <u>View report</u>









#### source: cargurus.co.uk

#### Entry 2

Date	2021-10-31
Pictures	0
Listing price	View report

### source: heycar.co.uk

### Entry 1

Date	2021-10-29	
CarCheck.co.uk		page 2/11

Pictures	0
Listing price	View report

source: autotrader.co.uk



**MOT** history

MOT expiry date	2024-11-01
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	9
Total items failed	4

MOT #6	2023-10-05 09:26
MOT test number	641824578339
Result	<b>✓</b> Passed
Next expiry date	2024-11-01

MOT test number

801188965763

Result

Fail Front Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #4	2022-11-02 12:05
MOT test number	678733152958
Result	✓ Passed
Advice Nearside Front and Offside Front tyres worn/bald on inner edge	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing Worn/misshape (ii))	ed Inner edge (5.2.3 (d)

CarCheck.co.uk page 3/11



**MOT #1** 

HJ18SVU report date: 2024-03-28

**MOT** #3 2021-11-02 09:29 298872930868 **MOT** test number Result ✓ Passed **Advice** Nearside Rear brake disc corroding Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice Advice** Offside Rear brake discs corroding Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #2** 2021-03-25 14:26 667583769559 **MOT test number** Result Passed

2021-03-25 10:30 **MOT** test number 134336858009 Result × Failed Fail Nearside Front Tyre has ply or cords exposed inner sidewall (5.2.3 (d) (ii))

**Advice** Offside Front tyre close to limit and cuts but no visible cord

CarCheck.co.uk page 4/11



# Tax & MOT check



Tax status	Valid until 1 December
Days left	217
MOT expiry date	1 November 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	Н
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



### Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



_		
Owne	 	
	ΙСΤ	nrv
	 IJL	

For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report	
***************************************	
THE STATE OF THE S	
***************************************	
	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 8/11



## Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2018-04-04
Last registration	2023-10-05
Complete history	See info



Registration #1	2018-04-04	22 mi
Registration #2	2021-03-25	21.262 mi
Registration #3	2021-03-25	21.265 mi
Registration #4		71.777 46
Registration #5		11.777 es
Registration #6		71.777 66
Registration #7		11.777 es
Registration #8		71.777 66
Registration #9		11.777 es
Registration #10		71.777 66
Registration #11		9.70 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 10/11



# Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	94%
Children	85%
Pedestrian	52%
Safety systems	86%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	2019 mm
Height	1608 mm
Length	4388 mm
Wheel base	2603 mm
Kerb weight	1580 kg
Max. allowed weight	2205 kg

# Additional information

Fuel tank capacity	64 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 1	1/11

Number of axles 2

Engine number DFTA101217