



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO GTI
Colour	Black
Year of manufacture	2015
Top speed	147 mph
0 - 100 km/h	6.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	141 kW / 192 HP / 189 BHP
Max. torque	250 Nm at 1.300 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-01-25
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	7
Total items failed	5

MOT #8	2024-01-26 13:01
MOT test number	901966364493
Result	✓ Passed
Next expiry date	2025-01-25
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge close to wear bars (5.2.3 (e))

MOT #7	2024-01-26 08:54
MOT test number	151375867403
Result	✗ Failed
Fail	Rear Shock absorbers has negligible damping effect (5.3.2 (d))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge close to wear bars (5.2.3 (e))
Fail	Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))
Fail	Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #6	2022-11-26 10:57
MOT test number	476344275572
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2021-11-26 16:37**MOT test number** 857207495333**Result** ✓ Passed**MOT #4** 2021-11-26 08:40**MOT test number** 682214266234**Result** ✗ Failed**Fail** Nearside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #3** 2020-07-18 12:45**MOT test number** 254009203142**Result** ✓ Passed**MOT #2** 2019-04-13 12:36**MOT test number** 986341394595**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))**MOT #1** 2018-05-02 14:31**MOT test number** 642652101489**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
25 January 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	25 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 YJ15YPM
Plate since	2015-05-29
Current registration	 YJ15YPM
Plate since	2015-05-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-07-30
Last registration	2024-01-26
Complete history	See info



Registration #1	2015-07-30	28 mi
Registration #2	2018-05-02	63.992 mi
Registration #3	2019-04-13	71.616 mi
Registration #4	2020-07-18	81.359 mi
Registration #5	2020-09-29	85.277 mi
Registration #6	2020-12-01	89.195 mi
Registration #7	2021-02-23	93.113 mi
Registration #8	2021-05-16	97.031 mi
Registration #9	2021-08-08	100.949 mi
Registration #10	2024-01-26	104.867 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1443 mm
Length	3983 mm
Wheel base	2468 mm
Kerb weight	1067 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	DAJ 010202