




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE DESIGN TSI BLUEMOTION TECHNOLO
Colour	White
Year of manufacture	2018
Top speed	112 mph
0 - 100 km/h	10.9 seconds
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 104 BHP
Max. torque	175 Nm at 1.400 rpm
Engine capacity	1.197 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	126 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-10-29
Pictures	8
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-01-30
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	4
Total items failed	7

MOT #6	2024-01-31 10:36
MOT test number	901507603241
Result	✓ Passed
Next expiry date	2025-01-30
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5	2023-01-25 16:56
MOT test number	183766910573
Result	✓ Passed

**MOT #4** 2023-01-24 11:24**MOT test number** 235628838467**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure on limit and cracking (5.2.3 (d) (ii))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Rear Rear fog lamp not working (4.5.1 (a) (ii))**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure on limit and cracking. (5.2.3 (d) (ii))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #3** 2021-11-04 16:22**MOT test number** 335622619184**Result** ✓ Passed**MOT #2** 2021-01-28 16:42**MOT test number** 991100412571**Result** ✓ Passed**MOT #1** 2021-01-28 13:45**MOT test number** 102693399549**Result** ✗ Failed**Fail** Offside Front Outer Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Outer Suspension arm pin or bush excessively worn (5.3.4 (a) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
30 January 2025

Tax status	Valid until 1 November
Days left	187
MOT expiry date	30 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 SM67MVX
Plate since	2019-06-29
Current registration	 SM67MVX
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-01-31
Last registration	2024-01-31
Complete history	See info



Registration #1	2018-01-31	27 mi
Registration #2	2021-01-28	21.245 mi
Registration #3	2021-01-28	21.246 mi
Registration #4	2024-01-31	21.246 mi
Registration #5	2024-01-31	21.246 mi
Registration #6	2024-01-31	21.246 mi
Registration #7	2024-01-31	21.246 mi
Registration #8	2024-01-31	21.246 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	90%
Pedestrian	53%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2021 mm
Height	1488 mm
Length	4288 mm
Wheel base	2524 mm
Kerb weight	1214 kg
Max. allowed weight	1760 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3

Number of axles

2

Engine number

CYVD590185
