



General information

Make	VOLVO
Model	XC70 D3 SE LUX AWD
Colour	Blue
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	41.5 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-07-31
Pictures	40
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-30
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	14
Total items failed	6

MOT #12	2024-01-04 14:56
MOT test number	202485766686
Result	✓ Passed
Next expiry date	2025-01-30
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Nail in tyre
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2023-01-27 12:44
MOT test number	682074960370
Result	✓ Passed

MOT #10	2022-01-17 14:12
MOT test number	986854912725
Result	✓ Passed

**MOT #9** 2021-01-19 11:40**MOT test number** 668534478968**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2020-01-31 16:01**MOT test number** 700059848896**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2020-01-29 09:29**MOT test number** 510898746770**Result** ✗ Failed**Fail** Offside Rear Direction indicator not working (4.4.1 (a) (ii))**Fail** Offside Rear Position lamp lens seriously defective (4.2.1 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2019-03-29 17:03**MOT test number** 753473790313**Result** ✓ Passed

**MOT #5** 2019-03-29 12:04**MOT test number** 503038210624**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #4** 2018-04-03 10:47**MOT test number** 254403253673**Result** ✓ Passed**MOT #3** 2017-04-01 08:47**MOT test number** 857294985041**Result** ✓ Passed**MOT #2** 2016-04-04 11:35**MOT test number** 768838733252**Result** ✓ Passed**MOT #1** 2015-03-31 13:22**MOT test number** 525580395008**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
30 January 2025

Tax status	Valid until 1 January
Days left	248
MOT expiry date	30 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-04-04
Last registration	2024-01-04
Complete history	See info



Registration #1	2012-04-04	12 mi
Registration #2	2015-03-31	20.285 mi
Registration #3	2016-04-04	26.506 mi
Registration #4	2017-04-01	32.882 mi
Registration #5	2018-04-03	50.466 mi
Registration #6	2019-03-29	80.375 mi
Registration #7	2019-03-29	80.375 mi
Registration #8	2020-03-29	80.375 mi
Registration #9	2020-03-29	80.375 mi
Registration #10	2020-03-29	80.375 mi
Registration #11	2020-03-29	80.375 mi
Registration #12	2020-03-29	80.375 mi
Registration #13	2020-03-29	80.375 mi
Registration #14	2020-03-29	80.375 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1861 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1891 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1133407